

CEN25LA188

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of the wind cone that was impacted by the airplane (courtesy of the Texas Department of Public Safety)



Photograph 2 - View of the wind cone that was impacted by the airplane (courtesy of the Texas Department of Public Safety)



Photograph 3 - View of the wind cone that was impacted by the airplane (courtesy of the Texas Department of Public Safety)



Photograph 4 - View of the wind cone that was impacted by the airplane at the segmented circle (courtesy of the Texas Department of Public Safety)



Photograph 5 - View of the front of the airplane (courtesy of the Texas Department of Public Safety)



Photograph 6 - View of the right side of the airplane (courtesy of the Texas Department of Public Safety)



Photograph 7 - View of the rear of the airplane (courtesy of the Texas Department of Public Safety)



Photograph 8 - View of the left side of the airplane (courtesy of the Texas Department of Public Safety)