

National Transportation Safety Board

Office of Aviation Safety
Central Region



CEN25LA353

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane Damage Sustained During Deer Strike (Courtesy of Pilot)



Photograph 2 - Left Wing Damage (Courtesy of Pilot)