

CEN25LA356

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Aerial view of the accident site (courtesy of the Texas Department of Public Safety)



Photograph 2 - Aerial view of the accident site (courtesy of the Texas Department of Public Safety)



Photograph 3 - View of the fuselage and the empennage at the accident site (courtesy of the Federal Aviation Administration)



Photograph 4 - View of the fuselage at the accident site (courtesy of the Federal Aviation Administration)



Photograph 5 - View of the empennage at the accident site (courtesy of the Federal Aviation Administration)



Photograph 6 - View of the cockpit at the accident site (courtesy of the Federal Aviation Administration)



Photograph 7 - View from the private heliport looking to the north (courtesy of the Federal Aviation Administration)



Photograph 8 - View of the private heliport lighting (courtesy of the Federal Aviation Administration)



Photograph 9 - View of the private heliport lighting and lighted wind cone (courtesy of the Federal Aviation Administration)



Photograph 10 - View from the private heliport looking to the northwest (courtesy of the Federal Aviation Administration)