

## Joshua Lindberg

---

**From:** [REDACTED].com>  
**Sent:** Monday, September 29, 2025 10:33 AM  
**To:** Joshua Lindberg  
**Subject:** Re: NTSB Investigation - N7774A Lancaster TX  
**Attachments:** 1000077753.jpg; 1000077744.jpg

[CAUTION] This email originated from outside of the organization. Do not click any links or open attachments unless you recognize the sender and know the content is safe.

Good morning Mr. Lindberg,

Thank you for assisting with this investigation.

Attached you will find:

A photo of the tachometer taken today (09/29/2025), showing 6538.21 hours.

A copy of the last annual inspection dated March 1, 2025, with the tachometer reading 6511.08.

We do not have a photo of the last 100-hour engine inspection, as the aircraft has not yet reached 100 hours since the last annual.

For your records:

Engine total time: 32 hours

Engine time since overhaul: 32 hours

Engine time since last inspection: 27 hours

Please let us know if you need any additional documents or information—we are ready to cooperate fully.

Thank you,

[REDACTED]

Skyway Aviators