

CEN25LA393

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane at accident site (Courtesy of FAA)



Photograph 2 - Side view of airplane at accident site (Courtesy of FAA)



Photograph 3 - Front view of airplane at accident site (Courtesy of FAA)



Photograph 4 - Fuel selector valve after removal from aircraft (Courtesy of FAA)