

CEN25LA396

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident site (Courtesy of pilot)



Photograph 2 - Powerline damage (Courtesy of pilot)