

NATIONAL TRANSPORTATION SAFETY BOARD • PILOT/OPERATOR AIRCRAFT ACCIDENT/INCIDENT**REPORT** Use this form (Form 6120.1) to report civil and public aircraft accidents and incidents**BASIC INFORMATION****Accident/Incident Location**Nearest City/Place: downers grove State: ilZIP: 60516 Country: usLatitude: 41.73238°N Longitude: 88.00035°W

(Enter in decimal degrees or degrees:minutes:seconds)

Accident/Incident Date/TimeDate: 11/28/2025 Local Time: 12:12
mm/dd/yyyy HH:MMTime Zone: cstCollision with Other Aircraft: ☐ Midair ☐ On-ground ☒ None**AIRCRAFT INFORMATION**Registration Number: 4332vManufacturer: cessnaModel: 195Serial Number: 7238Year of Manufacture: 1,948Amateur-Built: ☐ Yes ☒ No If Yes: ☐ Original Design ☐ Kit/Plans

Make: _____

- ☐
- IFR-Equipped and Certified
-
- ☐
- Commercial Space Flight
-
- ☐
- Unmanned Aircraft

Maximum Gross Weight: 3,350 lbs.Weight at Time of Accident/Incident: 3,260 lbs.Number of Seats: 5 Flight Crew Seats: 1Cabin Crew Seats: 0 Passenger Seats: 4Number of Engines: 1**Category of Aircraft**
(Select one)

- ☒
- Airplane
-
- ☐
- Balloon
-
- ☐
- Blimp/Dirigible
-
- ☐
- Glider
-
- ☐
- Gyroplane
-
- ☐
- Helicopter
-
- ☐
- Powered Lift
-
- ☐
- Rocket
-
- ☐
- Ultralight
-
- ☐
- Unknown

Type of Airworthiness Certificate
(Check all that apply)**Standard**

- ☒
- Normal
-
- ☐
- Aerobatic
-
- ☐
- Balloon
-
- ☐
- Commuter
-
- ☐
- Transport
-
- ☐
- Utility

Special

- ☐
- Restricted
-
- ☐
- Limited
-
- ☐
- Provisional
-
- ☐
- Special Flight
-
- ☐
- Experimental
-
- ☐
- Special Light-Sport
-
- ☐
- Experimental Light-Sport

- ☐
- Certificate of Authorization or Waiver (COA)
-
- ☐
- None
- ☐
- Unknown

Landing Gear

(Check all that apply)

- ☐
- Retractable
- ☐
- High Skid
-
- ☐
- Tricycle
- ☐
- Skid
-
- ☒
- Tailwheel
- ☐
- Ski/Wheel
-
- ☐
- Emergency Float
- ☐
- Hull
-
- ☐
- Float
- ☐
- Ski
-
- ☐
- Amphibian
- ☐
- Unknown
-
- ☐
- Other Launch/Recovery System
-
- ☐
- None

Engine Type (Select one)

- ☒
- Reciprocating
- ☐
- Liquid Rocket
-
- ☐
- Turbo Shaft
- ☐
- Solid Rocket
-
- ☐
- Turbo Prop
- ☐
- Hybrid Rocket
-
- ☐
- Turbo Jet
- ☐
- None
-
- ☐
- Turbo Fan
- ☐
- Unknown
-
- ☐
- Electric

Fuel System Type (Reciprocating)

- ☒
- Carburetor
- ☐
- Fuel Injected

Engine	Engine Manufacturer	Engine Model/Series	Engine Serial Number	Date of Mfg. (mm/dd/yyyy)	Rated Power ☒ Horsepower or ☐ Lbs. of Thrust	Total Time (hours)	Time Since: Inspection (hours)	Overhaul (hours)
Eng. 1	<u>jacobs</u>	<u>r755-a2</u>	<u>31119</u>		<u>300</u>	<u>2,389</u>	<u>47</u>	<u>139</u>
Eng. 2								
Eng. 3								
Eng. 4								

Last Inspection Type

- ☐
- 100-Hour
-
- ☐
- AAIP
-
- ☒
- Annual
-
- ☐
- Continuous Airworthiness
-
- ☐
- Condition
-
- ☐
- Unknown

Date of Last Inspection: 01/09/2025
mm/dd/yyyyAirframe Total Time: 3,769.5 hrs

Hours measured at (Select one)

- ☐
- Last Inspection
- ☒
- Time of Accident/Incident

Type of Maintenance Program (Select One)

- ☒
- Annual
-
- ☐
- Conditional (Amateur-built only)
-
- ☐
- Manufacturer's Inspection Program
-
- ☐
- Other Approved Inspection Program
-
- ☐
- (AAIP) Continuous Airworthiness
-
- ☐
- Other, specify: _____

Description of Fire Extinguishing System

- ☒
- None
-
- ☐
- Specify: _____

Additional Equipment

- ☒
- ADS-B
-
- ☐
- Airframe Parachute
-
- ☐
- Angle of Attack Indicator
-
- ☐
- Autopilot
-
- ☐
- Autopilot/FMS, Model: _____
-
- ☐
- Coupled Flight Director
-
- ☐
- Data Recorder
-
- ☐
- Device Stall Warning System
-
- ☒
- Electronic Flight Bag or Handheld Device
-
- ☐
- Electronic Multifunction Display
-
- ☐
- Electronic Primary Flight Display
-
- ☐
- Flight Management System

- ☒
- Handheld GPS
-
- ☐
- Heads Up Display
-
- ☐
- Night Vision Goggles
-
- ☒
- Onboard Weather
-
- ☐
- Primary Flight Display
-
- ☐
- SAS, Number of Axes: _____ Model: _____
-
- ☐
- Satellite Tracking Device
-
- ☐
- Stall Warning System
-
- ☐
- Video Recording Device
-
- ☐
- Wire Strike Detection
-
- ☐
- Wire Strike Protection
-
- ☐
- Other, Specify: _____

ELT Installed: ☒ Yes ☐ No If Yes:ELT Manufacturer: Emerg. Beacon Corp.Model or Part No.: EBC-102ATSO No.: ☒ C91 (121.5 MHz) ☐ C91a (121.5 MHz)
☐ C126 (406 MHz)Was ELT still mounted in aircraft? ☒ Yes ☐ NoWas ELT still connected to antenna? ☒ Yes ☐ NoDid ELT activate? ☐ Yes ☐ NoIf activated: Did ELT aid in locating aircraft? ☐ Yes ☐ NoIf not activated: Indicate Reason: ☐ Impact Damage☐ Fire Damage ☐ Battery Expired/Damaged ☐ Unknown**Propeller 1**

- ☐
- Fixed Pitch
-
- ☒
- Controllable Pitch
-
- ☐
- Ground Adjustable

Manufacturer: hamilton standardModel: 2b20**Propeller 2**

- ☐
- Fixed Pitch
-
- ☐
- Controllable Pitch
-
- ☐
- Ground Adjustable

Manufacturer: _____

Model: _____

OWNER/OPERATOR INFORMATION**Registered Aircraft Owner**

Name: [REDACTED]
 City: downers grove State: il
 ZIP: 60516 Country: us

Fractional Ownership Aircraft: ☐ Yes ☒ No

Operator of Aircraft

☒ The Operator is also the Registered Owner

☒ Same address as Registered Owner

Name: [REDACTED]
 City: downers grove State: il
 ZIP: 60516 Country: US

Doing Business As: _____

Air Carrier/Operator Designator (4-character code): _____

Operating Certificates Held

(Check all that apply)

- ☒ None
☐ Flag Carrier Operating Certificate (FAR 121)
☐ Supplemental
☐ Air Cargo
☐ Foreign Air Carriers (FAR 129)
☐ Rotorcraft External Load (FAR 133)
☐ Commuter Air Carrier (FAR 135)
☐ On-Demand Air Taxi (FAR 135)
☐ Commercial Air Tour (FAR 136)
☐ Agricultural Aircraft (FAR 137)
☐ Pilot School (FAR 141)
☐ Certificate of Authorization or Waiver (COA)
☐ Commercial Space Transportation
 Experimental Permit
☐ Commercial Space Transportation License
☐ Other Operator of Large Aircraft

Regulation Flight Conducted Under

- ☒ FAR 91 ☐ FAR 129 ☐ FAR 415
☐ FAR 103 ☐ FAR 133 ☐ FAR 431
☐ FAR 121 ☐ FAR 135 ☐ FAR 435
☐ FAR 125 ☐ FAR 137 ☐ FAR 437
☐ FAR 450
☐ FAR 91 Special Flight
☐ Non-US, Commercial
☐ Non-US, Non-commercial
☐ Public Aircraft (Select one)
 ☐ Armed Forces
 ☐ Federal
 ☐ State
 ☐ Local
☐ Unknown

Revenue Operation for FAR 121, 125, 129, 135

(Select one for each group)

- ☐ Scheduled or Commuter ☐ Domestic
☐ Non-Scheduled or Air Taxi ☐ International
☐ Passenger
☐ Cargo
☐ Mail Contract Only

Purpose of Flight for FAR 91, 103, 133, 137 (Select one)

- ☐ Aerial Application ☐ Firefighting
☐ Aerial Observation ☐ Flight Test
☐ Air Drop ☐ Glider Tow
☐ Air Race/Show ☐ Instructional
☐ Banner Tow ☐ Other Work Use
☐ Business ☒ Personal
☐ Executive/Corporate ☐ Positioning
☐ External Load ☐ Skydiving
☐ Ferry ☐ Unknown

Revenue Sightseeing Flight

☐ Yes ☒ No

Air Medical Flight

☐ Yes ☒ No

AIRPORT INFORMATION (Fill in if accident/incident occurred on approach, landing, takeoff, departure, or within 3 miles of an airport)

Airport Name: brookeridge airport
 Airport Identifier: I122
 Proximity to Airport: ☐ Off Airport/Airstrip ☒ On Airport/Airstrip ☐ N/A

Distance From Airport Center: 0.00 sm.
 Direction From Airport: 0.00 degrees true
 Airport Elevation: 749.00 ft. MSL

Runway Information

Runway ID: 27 Length: 2,813 ft. Width: 40 ft.

Runway/Landing Surface (Check all that apply)

- ☒ Asphalt ☒ Grass/Turf ☐ Ice ☐ Snow
☐ Concrete ☐ Gravel ☐ Macadam ☐ Water
☐ Dirt ☐ Helideck ☐ Metal/Wood ☐ Unknown
☐ Elevated Heliport ☐ Helistop ☐ Off-site landing area

Condition of Runway/Landing Surface (Check all that apply)

- ☒ Dry ☐ Snow-Compacted ☐ Water-Calm
☐ Holes ☐ Snow-Crusted ☐ Water-Choppy
☐ Ice Covered ☐ Snow-Dry ☐ Water-Glassy
☐ Rough ☐ Snow-Wet ☐ Wet
☐ Rubber Deposits ☐ Soft
☐ Slush-Covered ☐ Vegetation ☐ Unknown

Approach/Departure Segment (Select one)

- ☐ Taxi ☐ VFR Departure ☐ On Instrument Approach ☐ Downwind ☐ Low Approach
☐ Takeoff ☐ IFR Departure Procedure/Clearance ☐ Landing ☐ Base ☒ Go Around
☐ Initial Climb ☐ Aborted Landing (after touchdown)
☐ Crosswind ☐ Unknown

IFR Approach (Check all that apply)

- ☒ None
☐ ADF/NDB ☐ PAR ☐ MLS ☐ Practice
☐ SDF ☐ Sidestep ☐ LDA ☐ GPS
☐ VOR/TVOR ☐ ILS ☐ ASR ☐ Unknown
☐ VOR/DME ☐ Localizer Only ☐ Visual
☐ TACAN ☐ LOC-back course ☐ Contact
☐ RNAV ☐ Circling

VFR Approach (Check all that apply)

- ☐ None
☒ Traffic Pattern ☐ Stop and Go
☐ Straight-In ☐ Touch and Go
☐ Valley/Terrain Following ☐ Simulated Forced Landing
☒ Go Around ☐ Forced Landing
☐ Full Stop ☐ Precautionary Landing
☐ Unknown

"FLIGHT CREWMEMBER 1" INFORMATION**"Flight Crewmember 1" Responsibilities at the Time of Accident/Incident**

☒ Captain ☐ First Officer ☐ Pilot ☐ Co-Pilot ☐ Student Pilot ☐ Flight Instructor ☐ Check Pilot ☐ Flight Engineer ☐ Other Flight Crew

"Flight Crewmember 1" was pilot flying ☒ Yes ☐ No

"Flight Crewmember 1" Identification

First Name: [REDACTED]

City of Residence: downers grove

Middle Initial: [REDACTED]

State: il ZIP: 60516

Last Name: [REDACTED]

Country: us

Age at time of Accident/Incident: 68

Date of Birth: [REDACTED] (mm/dd/yyyy)

Certificate Number: [REDACTED]

Degree of Injury

☐ None ☐ Serious
☐ Unknown ☐ Fatal
☒ Minor

Seat Occupied

☒ Left ☐ Front ☐ Unknown
☐ Right ☐ Rear
☐ Center ☐ Single

Restraint Type**Available**

☐ None
☐ Lap only
☐ 3-point
☒ 4-point
☐ 5-point
☐ Unknown

Used

☐ None
☐ Lap only
☐ 3-point
☒ 4-point
☐ 5-point
☐ Unknown

Supplemental Restraint, specify: BAS shoulder

Inflatable Restraints

☒ Not Installed
☐ Installed
☐ Not Deployed
☐ Deployed
☐ Unknown

Pilot Certificate(s) (Check all that apply)

☐ None ☐ Flight Instructor ☐ Commercial
☐ US Military ☒ Private ☐ Recreational
☐ Airline Transport ☐ Foreign ☐ Sport
☐ Student ☐ Flight Engineer

Principal Occupation

☐ Pilot
☒ Other
☐ Unknown

Medical Certificate

☐ None ☐ Class 3
☐ Class 1 ☐ BasicMed
☒ Class 2 ☐ Driver's License (Sport Pilot only)

☐ Unknown

Medical Certificate Validity

☐ Without limitations/waivers ☐ Unknown
☒ With limitations/waivers ☐ N/A
☐ Special Issuance

Date of Last Medical

10/21/2025
 mm/dd/yyyy

Medical Certificate Limitations

must use corrective lens(es) to meet vision standards at all required distances.

Medical Certificate Special Limitations**Personal Flight Equipment** (Check all that apply)

☐ Fire resistant flight suit ☐ Helmet ☐ Laser protective visor/glasses ☐ Personal locator beacon(s) (PLB) ☐ Fire resistant gloves
☐ Helmet visor ☐ Night vision goggles ☐ Personal flotation ☐ Other: _____

Date of Last Flight Review or Equivalent, Including FAR 121/135 Checks:

08/25/2025
 mm/dd/yyyy

Flight Review Aircraft

Make: cessna

Model: 195

Airplane Rating(s)
(Check all that apply)

☒ Single-Engine Land
☐ Single-Engine Sea
☐ Multiengine Land
☐ Multiengine Sea

Other Aircraft Rating(s)
(Check all that apply)

☒ None
☐ Airship
☐ Balloon
☐ Glider
☐ Gyroplane
☐ Helicopter
☐ Powered Lift

Instrument Rating(s)
(Check all that apply)

☒ None
☐ Airplane
☐ Helicopter
☐ Powered Lift

Instructor Rating(s)
(Check all that apply)

☒ None ☐ Instrument Airplane
☐ Airplane Single-Engine ☐ Instrument Helicopter
☐ Airplane Multiengine ☐ Helicopter
☐ Gyroplane ☐ Glider
☐ Powered lift ☐ Sport

Type Ratings and Applicable Logbook Endorsements

tailwheel and high performance

Student Endorsements (Include dates)

Flight Time (Enter hours for each box)	All Aircraft	This Make & Model	Airplane Single Engine	Airplane Multiengine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air	Multi-engine Rotorcraft	Tail-wheel
						Actual	Simulated					
Total Time	618	410	618	0	17	0	15	0	0	0	0	495
Pilot in Command (PIC)	530	410	530	0	13	0	14	0	0	0	0	450
Time as Instructor	0	0	0	0	0	0	0	0	0	0	0	0
This Make/Model					11	0	1					
Last 90 Days	32	18	32	0	0	0	0	0	0	0	0	18
Last 30 Days	3	3	3	0	0	0	0	0	0	0	0	3
Last 24 Hours	1	1	1	0	0	0	0	0	0	0	0	1

"FLIGHT CREWMEMBER 2" INFORMATION**"Flight Crewmember 2" Responsibilities at the Time of Accident/Incident**

☐ Captain ☐ First Officer ☐ Pilot ☐ Co-Pilot ☐ Student Pilot ☐ Flight Instructor ☐ Check Pilot ☐ Flight Engineer ☐ Other Flight Crew

"Flight Crewmember 2" was pilot flying ☐ Yes ☐ No

"Flight Crewmember 2" Identification

First Name: _____

City of Residence: _____

Middle Initial: _____

State: _____ ZIP: _____

Last Name: _____

Country: _____

Age at time of Accident/Incident: _____

Date of Birth: _____ (mm/dd/yyyy)

Certificate Number: _____

Degree of Injury

☐ None ☐ Serious
☐ Unknown ☐ Fatal
☐ Minor

Seat Occupied

☐ Left ☐ Front ☐ Unknown
☐ Right ☐ Rear
☐ Center ☐ Single

Restraint Type**Available**

☐ None
☐ Lap only
☐ 3-point
☐ 4-point
☐ 5-point
☐ Unknown

Used

☐ None
☐ Lap only
☐ 3-point
☐ 4-point
☐ 5-point
☐ Unknown

Inflatable Restraints

☐ Not Installed
☐ Installed
☐ Not Deployed
☐ Deployed
☐ Unknown

Pilot Certificate(s) (Check all that apply)

☐ None ☐ Flight Instructor ☐ Commercial
☐ US Military ☐ Private ☐ Recreational
☐ Airline Transport ☐ Foreign ☐ Sport
☐ Student ☐ Flight Engineer

Supplemental Restraint, specify: _____

Principal Occupation

☐ Pilot
☐ Other
☐ Unknown

Medical Certificate

☐ None ☐ Class 3
☐ Class 1 ☐ BasicMed
☐ Class 2 ☐ Driver's License (Sport Pilot only)

☐ Unknown

Medical Certificate Validity

☐ Without limitations/waivers ☐ Unknown
☐ With limitations/waivers ☐ N/A
☐ Special Issuance

Date of Last Medical

 mm/dd/yyyy

Medical Certificate Limitations**Medical Certificate Special Limitations****Personal Flight Equipment** (Check all that apply)

☐ Fire resistant flight suit ☐ Helmet ☐ Laser protective visor/glasses ☐ Personal Locator Beacon(s) (PLB) ☐ Fire resistant gloves
☐ Helmet visor ☐ Night vision goggles ☐ Personal flotation ☐ Other: _____

Date of Last Flight Review or Equivalent, Including FAR 121/135 Checks:

 mm/dd/yyyy

Flight Review Aircraft

Make: _____

Model: _____

Airplane Rating(s)
(Check all that apply)

☐ Single-Engine Land
☐ Single-Engine Sea
☐ Multiengine Land
☐ Multiengine Sea

Other Aircraft Rating(s)
(Check all that apply)

☐ None
☐ Airship
☐ Balloon
☐ Glider
☐ Gyroplane
☐ Helicopter
☐ Powered Lift

Instrument Rating(s)
(Check all that apply)

☐ None
☐ Airplane
☐ Helicopter
☐ Powered Lift

Instructor Rating(s)
(Check all that apply)

☐ None ☐ Instrument Airplane
☐ Airplane Single-Engine ☐ Instrument Helicopter
☐ Airplane Multiengine ☐ Helicopter
☐ Gyroplane ☐ Glider
☐ Powered lift ☐ Sport

Type Ratings and Applicable Logbook Endorsements**Student Endorsements** (Include dates)

Flight Time (Enter hours for each box)	All Aircraft	This Make & Model	Airplane Single Engine	Airplane Multiengine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air	Multi-engine Rotorcraft	Tail-wheel
						Actual	Simulated					
Total Time												
Pilot in Command (PIC)												
Time as Instructor												
This Make/Model												
Last 90 Days												
Last 30 Days												
Last 24 Hours												

ADDITIONAL FLIGHT CREWMEMBERS (Exclusive of cabin crew, complete the following information.)																			
Additional Crewmember Information First Name: _____ City of Residence: _____ Middle Initial: _____ State: _____ Zip: _____ Last Name: _____ Country: _____			Seat Occupied ☐ Left ☐ Rear ☐ Center ☐ Single ☐ Right ☐ Unknown ☐ Front		Injury ☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown														
Personal Flight Equipment (Check all that apply) ☐ Fire resistant flight suit ☐ Helmet ☐ Laser protective visor/glasses ☐ Personal locator beacon(s) (PLB) ☐ Fire resistant gloves ☐ Helmet visor ☐ Night vision goggles ☐ Personal flotation ☐ Other: _____																			
Pilot Certificate(s) (Check all that apply) ☐ None ☐ Flight Instructor ☐ Commercial ☐ US Military ☐ Private ☐ Recreational ☐ Airline Transport ☐ Foreign ☐ Student ☐ Sport ☐ Flight Engineer			Restraint Type <table border="0" style="width:100%;"> <tr> <th style="text-align: left;">Available</th> <th style="text-align: left;">Used</th> </tr> <tr> <td>☐ None</td> <td>☐ None</td> </tr> <tr> <td>☐ Lap Only</td> <td>☐ Lap Only</td> </tr> <tr> <td>☐ 3-point</td> <td>☐ 3-point</td> </tr> <tr> <td>☐ 4-point</td> <td>☐ 4-point</td> </tr> <tr> <td>☐ 5-point</td> <td>☐ 5-point</td> </tr> <tr> <td>☐ Unknown</td> <td>☐ Unknown</td> </tr> </table> Supplemental Restraint, specify: _____		Available	Used	☐ None	☐ None	☐ Lap Only	☐ Lap Only	☐ 3-point	☐ 3-point	☐ 4-point	☐ 4-point	☐ 5-point	☐ 5-point	☐ Unknown	☐ Unknown	Inflatable Restraints ☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown
Available	Used																		
☐ None	☐ None																		
☐ Lap Only	☐ Lap Only																		
☐ 3-point	☐ 3-point																		
☐ 4-point	☐ 4-point																		
☐ 5-point	☐ 5-point																		
☐ Unknown	☐ Unknown																		
Type Rating/Endorsement for Accident/Incident Aircraft? ☐ Yes ☐ No		Total Flight Time at the Time of this Accident/Incident: _____ hrs.																	
Additional Crewmember Information First Name: _____ City of Residence: _____ Middle Initial: _____ State: _____ Zip: _____ Last Name: _____ Country: _____			Seat Occupied ☐ Left ☐ Rear ☐ Center ☐ Single ☐ Right ☐ Unknown ☐ Front		Injury ☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown														
Personal Flight Equipment (Check all that apply) ☐ Fire resistant flight suit ☐ Helmet ☐ Laser protective visor/glasses ☐ Personal Locator Beacon(s) (PLB) ☐ Fire resistant gloves ☐ Helmet visor ☐ Night vision goggles ☐ Personal flotation ☐ Other: _____																			
Pilot Certificate(s) (Check all that apply) ☐ None ☐ Flight Instructor ☐ Commercial ☐ US Military ☐ Private ☐ Recreational ☐ Airline Transport ☐ Foreign ☐ Student ☐ Sport ☐ Flight Engineer			Restraint Type <table border="0" style="width:100%;"> <tr> <th style="text-align: left;">Available</th> <th style="text-align: left;">Used</th> </tr> <tr> <td>☐ None</td> <td>☐ None</td> </tr> <tr> <td>☐ Lap Only</td> <td>☐ Lap Only</td> </tr> <tr> <td>☐ 3-point</td> <td>☐ 3-point</td> </tr> <tr> <td>☐ 4-point</td> <td>☐ 4-point</td> </tr> <tr> <td>☐ 5-point</td> <td>☐ 5-point</td> </tr> <tr> <td>☐ Unknown</td> <td>☐ Unknown</td> </tr> </table> Supplemental Restraint, specify: _____		Available	Used	☐ None	☐ None	☐ Lap Only	☐ Lap Only	☐ 3-point	☐ 3-point	☐ 4-point	☐ 4-point	☐ 5-point	☐ 5-point	☐ Unknown	☐ Unknown	Inflatable Restraints ☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown
Available	Used																		
☐ None	☐ None																		
☐ Lap Only	☐ Lap Only																		
☐ 3-point	☐ 3-point																		
☐ 4-point	☐ 4-point																		
☐ 5-point	☐ 5-point																		
☐ Unknown	☐ Unknown																		
Type Rating/Endorsement for Accident/Incident Aircraft? ☐ Yes ☐ No		Total Flight Time at the Time of this Accident/Incident: _____ hrs.																	

PASSENGER(S) / OTHER PERSONNEL (Include cabin crew; continue on separate sheet, if necessary.)																			
Number of Passengers <u>1</u>																			
Passenger Information	Seat	Injury	Restraint Type	Inflatable Restraints	Age														
First Name: [REDACTED] City: <u>Bradenton</u> Middle Initial: [REDACTED] State: <u>FL</u> Zip: _____ Last name: [REDACTED] Country: <u>US</u> ☐ Crew ☒ Passenger ☐ Other Personal Flight Equipment (Check all that apply) ☐ Fire resistant flight suit ☐ Helmet ☐ Laser protective visor/glasses ☐ PLB ☐ Fire resistant gloves ☐ Night vision goggles ☐ Helmet visor ☐ Personal flotation ☐ Other: _____	☐ Left ☐ Center ☒ Right ☐ Unknown Row: <u>1</u>	☐ None ☒ Minor ☐ Serious ☐ Fatal ☐ Unknown	<table border="0" style="width:100%;"> <tr> <th style="text-align: left;">Available</th> <th style="text-align: left;">Used</th> </tr> <tr> <td>☐ None</td> <td>☐ None</td> </tr> <tr> <td>☐ Lap Only</td> <td>☐ Lap Only</td> </tr> <tr> <td>☐ 3-point</td> <td>☐ 3-point</td> </tr> <tr> <td>☒ 4-point</td> <td>☒ 4-point</td> </tr> <tr> <td>☐ 5-point</td> <td>☐ 5-point</td> </tr> <tr> <td>☐ Unknown</td> <td>☐ Unknown</td> </tr> </table> Supplemental Restraint, specify: <u>BAS shoulder</u>	Available	Used	☐ None	☐ None	☐ Lap Only	☐ Lap Only	☐ 3-point	☐ 3-point	☒ 4-point	☒ 4-point	☐ 5-point	☐ 5-point	☐ Unknown	☐ Unknown	☒ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If under 5 years, ☐ Child Restraint ☐ Lap-Held ☐ Unknown
Available	Used																		
☐ None	☐ None																		
☐ Lap Only	☐ Lap Only																		
☐ 3-point	☐ 3-point																		
☒ 4-point	☒ 4-point																		
☐ 5-point	☐ 5-point																		
☐ Unknown	☐ Unknown																		

First Name: _____ City: _____ Middle Initial: _____ State: _____ Zip: _____ Last name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other Personal Flight Equipment (Check all that apply) ☐ Fire resistant flight suit ☐ Helmet ☐ Laser protective visor/glasses ☐ PLB ☐ Fire resistant gloves ☐ Night vision goggles ☐ Helmet visor ☐ Personal flotation ☐ Other: _____	☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Supplemental Restraint, specify: _____	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If under 5 years, ☐ Child Restraint ☐ Lap-Held ☐ Unknown
First Name: _____ City: _____ Middle Initial: _____ State: _____ Zip: _____ Last name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other Personal Flight Equipment (Check all that apply) ☐ Fire resistant flight suit ☐ Helmet ☐ Laser protective visor/glasses ☐ PLB ☐ Fire resistant gloves ☐ Night vision goggles ☐ Helmet visor ☐ Personal flotation ☐ Other: _____	☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Supplemental Restraint, specify: _____	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If under 5 years, ☐ Child Restraint ☐ Lap-Held ☐ Unknown
First Name: _____ City: _____ Middle Initial: _____ State: _____ Zip: _____ Last name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other Personal Flight Equipment (Check all that apply) ☐ Fire resistant flight suit ☐ Helmet ☐ Laser protective visor/glasses ☐ PLB ☐ Fire resistant gloves ☐ Night vision goggles ☐ Helmet visor ☐ Personal flotation ☐ Other: _____	☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Supplemental Restraint, specify: _____	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If under 5 years, ☐ Child Restraint ☐ Lap-Held ☐ Unknown

FLIGHT ITINERARY INFORMATION

Last Departure Point	Time of Departure	Flight Information	Destination	Type Flight Plan Filed
Airport ID: <u>LL22</u> City: <u>downers grove</u> State: <u>IL</u> Country: <u>US</u>	Time: <u>11:11</u> HH:MM Time Zone: <u>CST</u>	Flight Number: <u>4332V</u> Operating as Flight <u>4332V</u>	Airport ID: <u>LL22</u> City: <u>downers grove</u> State: <u>IL</u> Country: <u>US</u>	☒ None ☐ VFR/IFR ☐ Company VFR ☐ IFR ☐ Military VFR ☐ Unknown Activated? ☐ Yes ☐ No ☐ Unknown

Type of ATC Clearance/Service (Check all that apply)

- ☐ Certificate of Authorization ☐ Special VFR ☐ Special IFR ☐ VFR Flight Following ☐ Cruise
☒ VFR ☐ IFR ☐ VFR On Top ☐ Traffic Advisory ☐ Unknown / NA
☐ None

Airspace where the accident/incident occurred (Check all that apply)

- ☐ Class A ☒ Class G ☐ Military Operations Area (MOA) ☐ Special
☐ Class B ☐ Demo Area ☐ Airport Advisory Area ☐ Air Traffic Control Area
☐ Class C ☐ Warning Area ☐ Jet Training Area ☐ Unknown
☐ Class D ☐ Prohibited Area ☐ TRSA
☐ Class E ☐ Restricted Area ☐ FAR 93

Altitude of In-Flight Occurrence: 20 ft. MSL**WEATHER INFORMATION AT THE ACCIDENT/INCIDENT SITE****Source of Pilot Weather Information**

(Check all that apply)

- ☒ National Weather Service ☐ Company
☐ Flight Service Station ☐ Military
☐ TV/Radio ☐ Internet
☒ Automated Report ☐ None
☒ Electronic Flight Bag-Application: ☐ Unknown
 foreflight
☒ On-Board Weather

Weather Observation Facility

Facility ID: KLOT
 Observation Time: 11:56
 Time Zone: CST
 Distance from Accident Site: 9.00 nm
 Direction from Accident Site: 210.00 degrees true

Basic Conditions

- ☒ VMC
☐ IMC
☐ Unknown

Lowest Cloud Condition**Height**

_____ ft. AGL

Light Condition

- ☐ Dawn ☐ Dusk ☐ Dark Night ☐ Unknown
☒ Day ☐ Night ☐ Bright Night

Sky/Lowest Cloud Condition

- ☒ Clear ☐ Thin Broken
☐ Few ☐ Thin Overcast
☐ Partial ☐ Unknown
 Obscuration
☐ Scattered

Ceiling

- ☒ None (Clear)
☐ Broken
☐ Overcast
☐ Obscured
☐ Indefinite
☐ Unknown

Ceiling Height

_____ ft. AGL

Temperature: _____ (°C) or 10.6 (°F)Dewpoint: -8.00 (°C) or _____ (°F)**Altimeter Setting:**30.39 (Hg), or _____ (mb)**Wind Direction**

- ☐ Variable or
 Direction: 300.00
 degrees true

Wind Speed

- ☐ Calm
☐ Light and Variable
 or
 Speed: 10.0 kts

Wind Gusts

- ☒ Not Gusting
 or
 Speed: _____ kts

Visibility

10.0 miles
 RVR: _____ feet
 RVV: _____ miles
 Density Altitude: _____ ft.

Type of Precipitation (Check all that apply)

- ☒ None ☐ Drizzle ☐ Freezing Rain
☐ Rain ☐ Ice Pellets ☐ Snow Shower
☐ Snow ☐ Snow Pellets ☐ Ice Pellets Shower
☐ Hail ☐ Snow Grains ☐ Freezing Drizzle
☐ Rain Showers ☐ Ice Crystals

Restriction to Visibility (Check all that apply)

- ☒ None ☐ Fog
☐ Blowing Dust ☐ Ground Fog
☐ Blowing Sand ☐ Haze
☐ Blowing Snow ☐ Ice Fog
☐ Blowing Spray ☐ Smoke
☐ Dust ☐ Unknown

Icing Forecast

- | Amount | Type |
|---------------------------------------|-------------------------------|
| ☒ None | ☐ N/A |
| ☐ Trace | ☐ Rime |
| ☐ Light | ☐ Clear |
| ☐ Moderate | ☐ Mixed |
| ☐ Severe | ☐ Unknown |
| ☐ Unknown | |

Intensity of Precipitation

- ☐ Light
☐ Moderate
☐ Heavy
☒ N/A
☐ Unknown

Icing Actual

- | Amount | Type |
|---------------------------------------|-------------------------------|
| ☒ None | ☐ N/A |
| ☐ Trace | ☐ Rime |
| ☐ Light | ☐ Clear |
| ☐ Moderate | ☐ Mixed |
| ☐ Severe | ☐ Unknown |
| ☐ Unknown | |

Turbulence (Check all that apply)

- | Type | Severity |
|--|-----------------------------------|
| ☒ None | ☐ Light |
| ☐ Clear Air | ☐ Moderate |
| ☐ Terrain-Induced | ☐ Severe |
| ☐ Convective | ☐ Extreme |

NOTAMS (D and FDC), AIRMETS, SIGMETs, PIREPs in effect at the time of the accident/incident:

No NOTAMS for LL22. No AIRMETS, SIGMETs nor PIREPs for neither planned route nor actual route.

DAMAGE TO AIRCRAFT AND OTHER PROPERTY					
Aircraft Damage		Aircraft Fire		Aircraft Explosion	
☐ None	☒ Substantial	☒ None	☐ Both Ground and In-Flight	☒ None	☐ Both Ground and In-Flight
☐ Minor	☐ Destroyed	☐ In-Flight	☐ Fire at Unknown Time	☐ In-Flight	☐ Fire at Unknown Time
	☐ Unknown	☐ On-Ground	☐ Unknown	☐ On-Ground	☐ Unknown
Description of Damage to Aircraft and Other Property (Use additional sheet, if necessary.)					
The outboard half of the right wing was torn from the plane. The left wing was torn from the plane. The engine and cowling were torn from the plane. The upper skin of the fuselage above the pilot and co-pilot seats was torn off exposing the cockpit. The upper portion of the instrument panel and firewall were bent towards the pilot and co-pilot seats. A substantial portion of the skin of the fuselage is wrinkled. The fuselage landed on its right side at the conclusion of the accident. The fuselage, tail feathers and a portion of the remaining right wing were subsequently rolled on the mains and tail wheel and rolled on the three wheels down the taxiway into the hangar for storage. The right wing struck an evergreen tree, however, a witness was unable to observe any obvious damage. The plane skidded along grass causing damage.					
NARRATIVE HISTORY OF FLIGHT (Please type or print in ink.)					
Describe what occurred in chronological order, including circumstances leading to and nature of accident/incident. Describe terrain and include wreckage distribution sketch if pertinent. Attach extra sheets if needed. State departure time and location, services obtained, and intended destination. Provide as much detail as possible.					
The plane with the pilot and single passenger departed LL22 at approximately 11 AM on Friday, November 28, 2025. The planned and actual route was a circular clockwise path along the VFR flyway, returning to LL22. The plane departed to the west flying over Naper Aero LL10 airport. At approximately LL10, the ATIS for KDPA was obtained. An initial call to the KDPA tower was made, followed by establishing two-way radio communication. The flight continued through KDPA airspace in a northerly direction. The flight continued along the VFR flyway passing over the Northbrook OBK VOR. Prior to reaching the VPFTS waypoint on the lakefront, the ATIS for O'Hare KORD was obtained and the altimeter setting was updated accordingly. Upon reaching the VPFTS waypoint, Chicago Approach 120.55 was being monitored but not contacted. The route continued in a southerly direction along the lake front VFR flyway. After passing Midway KMDW airspace, the route continued along the southern edge of the Midway KMDW airspace in a western direction. Prior to reaching Lewis Airport KLOT, the ATIS information Tango was obtained for KLOT. The Tango information indicated winds of 280 at 8 kts gusting to 14 kts. Noting the airplanes analog clock indicated about 55 minutes past the hour, the pilot waited for the ATIS information to cycle one or two times. Upon obtaining information Uniform, the altimeter was updated to 30.39. The wind was now reported as 300 at 10 knots. Prior to reaching the Lewis airspace, the flight diverted towards a generally northerly direction towards Brookeridge LL22. Various position reports were made on LL22 CTAF 122.9, including approximately 5 and 10 miles south, southeast. Traffic reported departing Brookeridge on runway 9. In response, a position report was made with a request to confirm that winds at LL22 were 300 at 10 kts as reported by Lewis. A response was not received. However, ADSB-IN data showed a plane was departing LL22 on runway 27 and a radio call was received reporting that the plane was leaving the area to the west or northwest. Our flight continued, entering the 45 for left 27. Flaps were lowered about abeam 27. At about the same time the pilot requested for a sterile cockpit. On final for 27 the propeller control was advanced fully forward and trim was added as appropriate. The windsock at the east end of the airport was observed and appeared to be consistent with wind from 300. Approach speed was about 80 or 82 mph. The flare was made at about the beginning of the runway; power was reduced to idle and pitch was set up for a three-point landing. The mains touched first and there was the expected bounce. The plane was settling in for a landing with the longitude alignment maintained. One or two further bounces followed. This is not uncommon, particularly with the heavy landing gear. Further, the plane appeared to be settling in for a complete stop and longitudinal direction was maintained. However, at about midfield, it was not apparent whether the plane would come to a full stop before the end of the runway, which is adjacent a residential street. Therefore, a decision was made to go around. Full throttle was applied. Carb heat was closed. Unexpectedly, the longitude axis of the plane shifted approximately 30 or 45° to the left. The plane was low and slow. Shortly thereafter, it developed airspeed and was climbing. The plane was immediately in the path of an evergreen tree with a residential home to the left and a hangar building to the right and behind the Evergreen tree. The plane was roughly 15-25 feet AGL. The controls were heavy and a decision was made that there was not enough lift to climb above the tree nor bank hard right. A decision was made to continue straight estimating that the right side of the wing near the end board side would strike the tree. This was considered the best option under the circumstances. The right wing struck the tree (41.73238°N 88.00035°W), and the trajectory of the plane changed accordingly. The plane came to rest on the right side of the fuselage, short of the hanger. The master switch, ignition and, I believe, the mixture, were turned off. The fuel shut off valve was not within reach due to the plane being at the right side and the condition of the pilot. The windscreen was no					
OPERATOR/OWNER SAFETY RECOMMENDATION (How could this accident/incident have been prevented?)					
The accident may have been prevented if full throttle was not applied as quickly as it was for the go-around. It is expected that the engine initially stumbled or faltered. Had the throttle been applied less quickly, that may have allowed the engine to spool up more quickly, than it did, providing full power of 300 HP to climb out for the go-around. Further to this point, assuming the throttle was advanced as the plane was in a downward movement toward the runway, prior to the engine spooling up for the climb out, the left main wheel may have impacted the runway causing the heading of the airplane to shift to the left. While impact with the left wheel in this manner was not detected, it is one logical conclusion. Additionally, I neglected to activate the noise cancelling feature on my Bose headsets for the flight. The additional background noise undoubtedly masked some of the sensory inputs. I am not certain how this accident occurred. The above recommendation is a good faith attempt to respond within the required 10-day period based on the facts as understood.					

MECHANICAL MALFUNCTION/FAILURE (If more space is needed, continue on a separate sheet.)Was there Mechanical Malfunction/Failure? ☐ Yes ☒ No

(If yes, list the name of the part, manufacturer, part no., serial no., and describe the failure.)

Total Time/ Cycles On Part

_____ Hours

_____ Cycles

Time Since This Part Inspected/Overhauled

_____ Hours

FUEL & SERVICES INFORMATION

Fuel on Board at Last Takeoff

(Convert from pounds, as necessary)

45.0 Gallons

Fuel Type

☒ 100 Low Lead☐ Automotive☐ Jet A☐ Jet A-1☐ Unleaded AV☐ Other, specify _____

Other Services, if any, prior to departure:

EVACUATION OF AIRCRAFTWas an emergency evacuation of the aircraft performed? ☒ Yes ☐ No

Method of Exit – Describe how the occupants exited and how many occupants evacuated each location:

The windscreen was no longer present. The passenger egress through the windscreen on the right side. The pilot then exited the plane also through the windscreen on the right side. The pilot and passenger both remained a safe distance from the plane.

OTHER AIRCRAFT – COLLISION (If air or ground collision occurred, complete this section for *other* aircraft.)

Aircraft Registration Number

Manufacturer: _____

Damage to Other Aircraft:

☐ Destroyed☐ Minor☐ Substantial☐ None

Model: _____

Registered Owner of Other Aircraft

Pilot of Other Aircraft

Name: _____

Name: _____

City: _____

City: _____

State: _____ ZIP: _____

State: _____ ZIP: _____

Country: _____

Country: _____

ADDITIONAL INFORMATION (Additional space for answers to any question.)

Continued from page 8: The windscreen was no longer present. The passenger egress through the windscreen opening on the right side. The pilot had to extract his legs which appeared to be stuck perhaps within the rudder pedals. The pilot then exited the plane also through the windscreen opening on the right side. After stumbling a safe distance from the plane, the pilot collapsed in pain and remained on this back. The pilot did not examine the crash site.

I HEREBY CERTIFY THAT THE ABOVE INFORMATION IS COMPLETE AND ACCURATE TO THE BEST OF MY KNOWLEDGE.

I understand that the information provided may be subject to public release.

Date of this report:

12/07/2025

mm/dd/yyyy

Name of Pilot/Operator

Signature:

-or- ☒ Check here to electronically sign this document

If a person other than Pilot/Operator is filing this report

Name: _____

Title: _____

Signature: _____

-or- ☐ Check here to electronically sign this document

FOR NTSB USE ONLY

NTSB Accident/Incident No.	Reviewed by NTSB AS Division	Name of Investigator	Date Report Received
CEN26LA056	CENTRAL	LINDBERG	12/07/2025