

CEN26LA146

INVESTIGATION PHOTOGRAPHS



Photograph 1 - N7548P in field (Courtesy of owner)



**Photograph 2 - Right wing as removed for transport showing wing spar damage
(Courtesy of NTSB)**