

BELOIT

MORITZ MEML (K61) 1 NW UTC-6(-5DT) N39°28.34' W98°07.70'

1418 B NOTAM FILE ICT

RWY 17-35: H4200X75 (CONC) S-30, D-30 PCN 11 R/C/X/U MIRL

RWY 17: PAPI(P2L)—GA 4.0° TCH 40'. Thld displcd 181'. Road.

RWY 35: PAPI(P2L)—GA 3.0° TCH 40'. Pole.

RWY 04-22: 2340X120 (TURF)

RWY 04: Pole.

RUNWAY DECLARED DISTANCE INFORMATION

RWY 17: TORA-4200 TODA-4200 ASDA-4200 LDA-4018

RWY 35: TORA-4200 TODA-4200 ASDA-4200 LDA-4200

SERVICE: S4 FUEL 100LL, JET A LGT ACTVT MIRL 17-35; PAPI Rwy 17 and 35—CTAF.

AIRPORT REMARKS: Attended Mon-Sat 1400-0000Z+. Fuel avbl H24 with credit card; svc aft hr - amgr. Glider ops on arpt. Rdo ctl ops on and invof aprt; wkend and hol. Rwy 04-22 red and white L mkr with reflector raised panels.

AIRPORT MANAGER: 785-738-7437

WEATHER DATA SOURCES: AWOS-3PT 118.225 (785) 378-4173.

COMMUNICATIONS: CTAF/UNICOM 122.8

® **KANSAS CITY CENTER APP/DEP CON** 134.9

CLEARANCE DELIVERY PHONE: For CD ctc Kansas City ARTCC at 913-254-8508.

RADIO AIDS TO NAVIGATION: NOTAM FILE ICT.

MANKATO (L) TACAN Chan 35 TKO (109.8) N39°48.38' W98°15.60' 153° 20.9 NM to fld. 1880/10E.

WICHITA

L-10H

IAP

