



Brian Rutt
Air Safety Investigator
AS-CEN

Date: April 14, 2026

Subject: CEN26LA165

Contact: Inspector [REDACTED], FAA

Inspector [REDACTED] reported that on-scene examination of N495LP revealed no indication of mechanical failure. Inspector [REDACTED] found no fuel in the fuel tank and only about ½ teaspoon of fuel was collected at the fuel sump. ///END OF STATEMENT///