

NATIONAL TRANSPORTATION SAFETY BOARD

RETENTION / RELEASE OF WRECKAGE RELATED TO ACCIDENT NUMBER ►

ACCIDENT NUMBER:

DCA14FA058

For Use In All Modal Investigations

REGISTERED OWNER (name and address) Trans States Airlines		IDENTIFICATION NUMBER N802HK	
		MAKE Embraer	
LOCATION Memphis, TN	DATE OF ACCIDENT 2/5/14	MODEL EMB 145	
RETAINED BY NTSB REPRESENTATIVE Adam Huray		TITLE AS-40	DATE 2/5/14
The National Transportation Safety Board has ☒ has not ☐ completed its investigation of the wreckage described above. All recovered wreckage except that listed in the evidence control form(s) is hereby released. ☐ NO PARTS RETAINED			
RELEASED BY NTSB REPRESENTATIVE Adam Huray		TITLE AS-40	DATE 8/4/16
(This section may be acknowledged by a person, not the owner or owner's representative, who has knowledge of the disposition of the recovered wreckage and its parts. Such acknowledgement does not place responsibility for disposition of the wreckage upon that person.) I HEREBY ACKNOWLEDGE: ☒ Receipt of the above described wreckage. ☐ Removal of the parts, if any, listed in the evidence control form(s).			
PERSON MAKING ACKNOWLEDGEMENT Matt Conrad		TITLE Director of Safety	DATE 9/12/2016
ADDRESS [REDACTED]		PHONE NUMBER & EMAIL [REDACTED]	
REMARKS: The parts listed below have been released back to Trans States Airlines. Ice Detector P/N 0871HT3-1A; S/N 00398 Ice Detector P/N 0871HT3-1A; S/N 02401 Data Acquisition Unit P/N 7013348-949; S/N 00063498 Data Acquisition Unit P/N 7013348-949; S/N 01094663 Navigation Unit RNZ-851 P/N 7510100-631; S/N 02066575 Navigation Unit RNZ-851 P/N 7510100-633; S/N 00054356 Position Transducer P/N D370535; S/N 00K02405 Position Transducer P/N D370535; S/N 01B01148 Position Transducer P/N D370535; S/N 00K02407 Area Microphone P/N 98Q-6113-005, S/N 0753			