

ATA: 5513	Pos: LH	Log Page: 7865789	Disc Type: NON ROUTINE LINE	Stage Flight: INSPECT/MAINT	STA: EWR
DISCREPANCY	1/27/2016	CLOSED LOG 7865789 FLT/CHK LINE NON ROUTINE LINE RPTD BY GLOPPEN 147896 STA EWR 27JAN16 LT HORIZ. STAB TIP FOUND DAMAGED, REF LOG # 7865786			
CORRECTION	1/27/2016	CORR BY GLOPPEN 147896 STA EWR 27JAN16 ATA 5513 POS: LH TASK HRS: 0001.0 TASK ELAPSE TIME HRS: 0001.0 RII: N INSTALLED LT HORIZONTAL STAB TIP PER STAMANDARD PREACTICES 2040			
CORRECTION	1/27/2016	ALTD BY DEANE 370957 STA ATG 27JAN16 - ATA CODE NUMBER CHANGED FROM: 2730 TO: 5513			
ATA: 5552	Pos: LH	Log Page: 7865786	Disc Type: PILOT REPORT	Stage Flight: INSPECT/MAINT	STA: EWR
DISCREPANCY	1/27/2016	CLOSED LOG 7865786 FLT/CHK 1409 PILOT REPORT RPTD BY DAIGLE 028294 STA EWR 27JAN16 WHILE PARKED ON DELTA RAMP IN EWR , WE FELT A LARGE SHUDDER THROUGH TH AIRCRAFT AS A DELTA B767 WAS BEING TOWED BEHIND US PLEASE INSPECT TAIL FOR DAMAGE CORR BY PATEL 836909 STA EWR 27JAN16 ATA 5552			
CORRECTION	1/27/2016	CORR BY PAGAN 913913 STA EWR 27JAN16 ATA 5552 POS: LH TASK HRS: 0024.0 TASK ELAPSE TIME HRS: 0024.0 RII: Y PERFORMED GVI LH REMOVED ELEVATOR ATTACH POINTS AND LH STAB SURFACES FND OUTBD HINGE BRACKET AND FAIRING DAMAGED .440684 WORKING PRI 543475-14 REV 0 C/W STEP 1-5 388732 C/W WITH PRI 543475-14 REV O 388732 C/W AMDS 2730-4590 LH 388732 C/W ALL RII INSP PER AMDS CARD 2730-4590-LH 513126 C/W ERA 543475-14 REV ORIG ALL RII C/W TAB, ELEVATOR; OFF 88-5525-9-0003 53409 ON 88-5525-9-0003 53370 ELEVATOR, LH SU OFF 88-5520-9-0003 53417 ON 88-5520-9-0011 00656			
CORRECTION	1/27/2016	ALTD BY EVANS 746669 STA ATG 27JAN16 . ATA CODE NUMBER CHANGED FROM: 2730 TO: 5552			