

Email received from MSgt. Graul, DATCF Chief Controller, on 8/24/16:

Mr. Dunham,

Since last we spoke I was engaged with Mrs Wrede at RAP tower. RAP tower is changing their procedures to specify that aircraft arriving from the north will not be issued landing clearance until past Ellsworth AFB. Additionally, we have changed our facility operating instruction to include the following guidance:

. Ensures pilots arriving north of RCA on a Visual Approach to RAP report both airfields in sight, except for pilots that report that they are familiar with the local area.

In regards to the MSAW issue, we spoke with OSF and I attached their response. They indicated that SATORI playback isn't necessarily indicating STARS behavior.

v/r

ROY E GRAUL, MSgt, USAF
DATCF, Chief Controller
Ellsworth AFB, SD