

MaintTran	TransDate	AircraftID	StationID	TimeDown	TimeUp	EntryType
15146624	5/19/2017 1:39	N796SK	FAT	6/15/2017	6/15/2017	Mx Rec

Reli_Discrep	Reli_CorrAction	ATACode	Squawk	ScheduleDate	DateCompleted
Left engine fuel drain tube from OBV to gang drain has 2 broken clamps.	Removed and replaced broken clamps on fuel drain tube in ref to CRJ700 AMM 73-11-09.	7170	Maint	5/18/2017	5/18/2017

MRB	Failure	Inspection	RowModDate	TransNum	Version	ACTailNum	ACSerialNo	Station
731000-202	Y	A1 INSP	6/15/2017 4:30	15146624	1	N796SK	10300	FAT

TAT	TAC
-----	-----

22,087.30	12912
-----------	-------