

SkyWest CRJ-700, N796SK, Uncontrolled Fire
Investigation Progress Meeting

NTSB Case No. DCA17LA182

GE Aviation North Pointe 1 Engineering Center
West Chester, Ohio
June 5 - 7, 2018

Day 1

June 5, 2018

Time	Topic	Presenter
0830 - 0845	Greeting / Introductions	GE / NTSB IIC
	Cincinnati (October 2017 Meeting) Action Items Review	NTSB
	Update on sister engine and latest field return data	Parker
1000 - 1015	BREAK	
	Link field Inspection Findings / Summary	BA Shorts
	GE assessment of BA Shorts investigation and link wear root cause	GE
1130 - 1230	LUNCH	
	Event Aircraft Stage 10 Plenum Air Seal & Plate Findings / Summary	BA Shorts
	GE assessment of BA Shorts Air Seal investigation	
1430 - 1545	BREAK	
	SB 75-0019 (CF34-8C) Field Containment Program Update	GE
	SB 75-0020 (CF34-8C) Repetitive Inspection Program Update	GE
	Updated GE Risk Assessment	GE
	FAA Forum	FAA
	Day 1 Action Items Review	NTSB

Day 2

June 6, 2018

Time	Topic	Presenter
0830 - 0930	SB 75-0016 (CF34-8E) Field Inspection Program Update	GE
0930 - 0945	BREAK	
	Bombardier Representatives join the Meeting	
	Review of Previous Day's minutes	NTSB
	Manual Updates (Aircraft, Engine and Component levels)	BA / GE / Parker
	LMM (Links & OBV Installations), ESM, and CMM	
1130 - 1230	LUNCH	
	Failure Analysis (FA) summary on Field Return OBV's	GE
1400 - 1415	BREAK	
	OBV Re-Design Program Update	GE
	Day 2 Action Items Review	NTSB
	Action Items Review	NTSB

Day 3			
June 7, 2018			
	Time	Topic	Presenter
	0830 - 0845	Review of Previous Day's minutes	NTSB
		Bombardier Updates	BA
	0930 - 0945	BREAK	
		Day 3 Action Items Review	NTSB
		Action Items Review	NTSB
		MEETING ADJOURN	