

On descent into HNL, our pos 1 took a call from the flight deck. He informed us that the captain said there would be slight to moderate turbulence and to make sure everything was put away. The captain made a PA stating that there could be some turbulence and to be seated and fasten your seatbelt and the pos 1 made a seatbelt PA. I never heard that the flight attendants needed to take a seat. I was pos 7 and I had all of my service items mostly picked up in business class. I was sitting in my jump seat at 2L aft facing chatting with pos 9 when the severe turbulence started. We immediately fastened our seatbelts. It did not last long. I was unhurt. A few of our business class passengers were upset but no one was hurt. I found out that 2 of my coworkers were hurt when I heard the captain make a PA stating that paramedics were meeting our flight. Pos 1 made the medical assistance PA and a business class passenger offered assistance. I escorted her to the back galley and realized they had plenty of help. Pos 1 asked me to bring the EMK because the attending medical personnel wanted the blood pressure cuff. I retrieved it and took it to the back galley. I then returned to business class to finish preparing for landing. We landed safely.