



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Washington, D.C. 20594

December 11, 2019

Attachment 5 – Turbulence ACARS Messages

OPERATIONAL FACTORS

DCA19CA091

17Feb2019 22:57 / 17Feb2019 22:57:20	- 41 TP SE09 172210Z 1.MS AL GA TN 2.* ADVISORY * VOR:BWG YOCKY MCN SQS HAZ:TURBC-OTHER SOURCE:PIREPS AREA:37N086W 37N083W 33N083W 34N091W TIME:POSN AT 17/2210Z ALTS:150-FL320 LGT/MOD MVG FROM:27025 INFO:FAST MOVG RAINSHWRS. MOST TOPS AOB FL250..ISLD TO FL320. CELLS MVG NE 60KTS 3.VALID 172210Z/180300Z 4.CANCEL SE08 ALONG ROUTE ENTER 17/2357Z BNA293025 EXIT 18/0034Z KATL ; 02172257/02172257 P99999 999
17Feb2019 23:05 / 17Feb2019 23:05:13	AAAA 1.MS AL GA TN 2.* ADVISORY * VOR:BWG RDU MCN SQS HAZ:TURBC-OTHER SOURCE:PIREPS AREA:37N086W 37N079W 33N083W 34N091W TIME:POSN AT 17/2302Z ALTS:150-FL350 LGT/MOD MVG FROM:27025 INFO:FAST MOVG RAINSHWRS. MOST TOPS AOB FL250..ISLD TO FL320. CELLS MVG NE 60KTS 3.VALID 172303Z/180300Z 4.CANCEL SE09 ALONG ROUTE ENTER 17/2357Z BNA293025

	EXIT 18/0034Z KATL ; 02172305/02172305 P99999 999
18Feb2019 00:12 / 18Feb2019 00:12:11	A MOD TURB. FA INJURED. REQUEST PARAMEDIC MEET PLANE AT C43. INJURED FA EMP NUM ; 02180012/02180012 P99999 999
18Feb2019 00:14 / 18Feb2019 00:14:08	- 44 A RE: DL957/17 BZN ATL COPY TITLE: FLIGHT SUPERINTENDENT ; 02180014/02180014 P99999 999
18Feb2019 00:16 / 18Feb2019 00:16:03	- 44 A RE: DL957/17 BZN ATL IS SHE ABLE TO PERFORM HER DUTIES? TITLE: FLIGHT SUPERINTENDENT ; 02180016/02180016 P99999 999
18Feb2019 00:19 / 18Feb2019 00:19:31	A NO ; 02180019/02180019 P99999 999