



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Washington, D.C. 20594

December 13, 2019

Attachment 3- Final Weather Briefing

SPECIALIST REPORT

DCA19CA213

06SEP19 NKS967 KCLE - KRSW

NK967 06SEP19 CLE-RSW

KCLE -CLE - CLEVELAND-HOPKINS INTL

06L/24R 9000 06R/24L 9956 10/28 6018

SA 061551Z 17003KT 10SM SCT110 23/11 A2991 RMK AO2 SLP126
T02330111 \$=SA 061451Z 00000KT 10SM SCT100 22/13 A2993 RMK AO2 SLP132
T02170128 58022 \$=SA 061351Z 24003KT 10SM SCT080 19/13 A2996 RMK AO2 SLP143
T01890128 \$=

FT 061524Z 0615/0718 22004KT P6SM SCT100

FM061800 36006KT P6SM SCT050 BKN100

FM062000 36007KT P6SM BKN060

FM070000 02005KT P6SM OVC050=

KRSW -RSW - SOUTHWEST FLORIDA INTL

06/24 12000

SA 061553Z 29007KT 10SM FEW030 SCT037 33/25 A2997 RMK AO2
SLP145 T03280250=SA 061453Z 28008KT 10SM FEW028 FEW037 32/24 A2998 RMK AO2
SLP149 T03170244 51009=SA 061353Z 28008KT 10SM SCT028 30/24 A2998 RMK AO2 SLP148
T03000239=

FT 061120Z 0612/0712 27012KT P6SM SCT030 SCT250

FM070100 23004KT P6SM FEW025 FEW250=

KSFB -SFB - ORLANDO SANFORD INTERNATIONAL

36/18 6002 09C/27C 3578 09L/27R 11002 09R/27L 5839

SA 061553Z 24009KT 10SM FEW029 32/24 A2991 RMK AO2 SLP128
T03220239=SA 061453Z 26009KT 10SM BKN020 BKN026 31/25 A2992 RMK AO2
SLP130 T03110250 51006=

SP 061502Z 23008KT 10SM SCT022 32/25 A2992 RMK AO2 T03170250=

SA 061353Z 24010KT 10SM BKN014 BKN020 30/26 A2991 RMK AO2
SLP127 T03000261=SP 061404Z 25007KT 10SM BKN016 BKN021 30/26 A2991 RMK AO2
T03000256=

SP 061445Z 24007KT 10SM SCT020 31/26 A2992 RMK AO2 T03110256=

FT 061120Z 0612/0712 24009KT P6SM BKN250

FM061400 28011KT P6SM FEW035 SCT250

FM070300 25005KT P6SM SKC=

PR 061605Z ARP UAL2140 4121N 08209W 1605 F360 TB SMTH IC

PR 061605Z ARP UAL2140 4121N 08209W 1605 F360 TB SMTH IC

PR 061512Z CMH UA /OV 20 SE APE/TM 1512/FL100/TP E190/TB MOD
TBPR 061530Z CMH UA /OV 20 E CMH/TM 1530/FLDURD/TP E75S/TB LGT
CHOP 080-120PR 061350Z CAE UA /OV CAE345020/TM 1350/FL260/TP B738/TB LGT
TO OCNL MOD CHOP 260-280 DURCPR 061556Z CWV UA /OV SAV280034 /TM 1556 /FL045 /TP SR22 /SK
SKC /WX FV99SM /WV 29012KT /TB OCNL LGTPR 061503Z AMG UA /OV AMG160030/TM 1503/FL210/TP G280/SK
SKC/TB LGT CHOP/IC NEG

PR 061503Z AMG UA /OV AMG160030/TM 1503/FL210/TP G280/SK
SKC/TB LGT CHOP/IC NEG

PR 061322Z OCF UA /OV OCF/TM 1322/FL210/TP B737/SK SKC/TB NEG

PR 061319Z ORL UA /OV ORL /TM 1319/FLDURD/TP C172/SK BKN012
SCT OVER FIELD

PR 061320Z SFB UA /OV 2NM WEST SFB/TM 1320/FL011/TP PA44/SK
SCT/RM PA44 REPORTED BASES 2NM WEST SFB SCT011

PR 061400Z ORL UA /OV ORL090010/TM 1400/FL016/TP C172/SK
BKN015

PR 061438Z MCO UA /OV MCO/TM 1438/FLUNKN/TP A321/SK
SCT020-TOP100/RM DURC

PR 061526Z ISM UA /OV ISM18005/TM 1526/FL022/TP C172/SK BKN022

PR 061526Z ORL UA /OV ORL/TM 1526/FL022/TP C560/SK BASES 022

PR 061349Z PIE UA /OV PIE180002/TM 1349/FL012/TP P28A/SK
SCT012

PR 061400Z PIE UA /OV PIE180004/TM 1400/FL015/TP A320/SK
BKN015

PR 061446Z PIE UA /OV 5S PIE/TM 1446/FL020/TP C56X/SK BKN020

PR 061501Z PIE UA /OV 5S PIE/TM 1501/FL018/TP PC12/SK BKN018