



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Washington, D.C. 20594

April 23, 2020

Attachment 14 – Aircraft Maintenance Log Entries

OPERATIONAL FACTORS

DCA20CA071

AIRWORTHINESS RELEASE		DATE:	STA:	TIME:	EMPLOYEE #:	SIGNATURE:
Discrepancy			Action Taken			
Item # 1	FLT # 5206	STA: CVG	STA: CVG	M/Hrs: 1.5	Date: 3/4/20	ATA: 15-20
2A Head rest came off checked			Deferred per sent 8A per MEL 15-21-C1 Cat "D"			
Signature: [Redacted]			Date: 2/4/20			
MPN OFF:			MSN OFF:			
MPN ON:			MSN ON:			
TECH SIGNATURE / #			[Redacted]			
Item # 2	FLT # 5634	STA: TYS	STA: TYS	M/Hrs: 1.5	Date: 2/7/2020	ATA: 05-50
Encountered severe turbulence in descent while passing through FL190.			PERFORMED VISUAL INSPECTION FOR SEVERE TURBULENCE, BUFFETING OR MANEUVER DAMAGE FAW CAT 900 AMM 05-51-C3-210-601, ONE BROKEN CEILING PANEL AND TWO BROKEN OVER HEAD BIN ARMS. SEE NOTES FOR THESE ITEMS, NO OTHER DAMAGE NOTED. FDR TO BE ACCOMPLISHED			
Signature: [Redacted]			Date: 2-7-20			
MPN OFF:			MSN OFF:			
MPN ON:			MSN ON:			
TECH SIGNATURE / #			[Redacted]			
Item # 3	FLT # 5634	STA: TYS	STA: TYS	M/Hrs: 1.0	Date: 2/11/2020	ATA: 35-30
Aft Emergency Portable O2 bottle used during flight			SERVICED AFT PORTABLE O2 BOTTLE TO PROPER PRESSURE FAW CRJ 900 VEMM 35-30-19			
Signature: [Redacted]			Date: 2-7-20			
MPN OFF:			MSN OFF:			
MPN ON:			MSN ON:			
TECH SIGNATURE / #			[Redacted]			
Item # 4	FLT # MX	STA: TYS	STA: TYS	M/Hrs: .3	Date: 2/7/2020	ATA: 25-00
OVER HEAD BIN 18/19 DF Door AFT HINGE ARM IS BROKE			DEFERRED OVER HEAD BIN 18/19 DF PER MEL 25-23-01 CAT "C" Complied with "m" function			
Signature: [Redacted]			Date: 2/7/2020			
MPN OFF:			MSN OFF:			
MPN ON:			MSN ON:			
TECH SIGNATURE / #			[Redacted]			