

Silva, Sathya

From: Nicholas Kleoppel [REDACTED]
Sent: Friday, June 17, 2022 1:56 PM
To: Silva, Sathya
Subject: Re: Hyannis Air Service - N833CA - Substantial Damage

[CAUTION] This email originated from outside of the organization. Do not click any links or open attachments unless you recognize the sender and know the content is safe.

Hello,

Here is the account from the pilot.

I was operating a flight on a maintenance ferry permit from KORD to KSTL. I was cleared to lineup and wait on runway 28R at N5 intersection behind a departing B737. The preceding aircraft was several 100 feet down the runway when I crossed the hold line. I had moved only a few feet when my right wing was lifted raising the right landing gear completely off the ground. The left wingtip contacted the ground and the aircraft pivoted about 45 degrees to the left. It only lasted a few seconds. I exited the runway at EE intersection and returned to Signature flight support.

I will begin working on the 6120 and will provide once all data/info is acquired.

Regards,
Nick