

DCA23FA417

MAINTENANCE

Group Chair's Factual Report - Attachment 1

Alaska Airlines AD Record

April 29, 2024

AD Number...	2019-01-03	<u>Status</u>
Subject	MLG FWD and AFT trunnion pin assy inspection Supersedes AD# 2016-18-01.	Terminated

AD Compliance

Compliance Date

Controlled by EC AD20161801-NG-32 (G1 and G2) and AD20190103-NG-32 (G5 and G6)

Paragraph (g), repetitive lube are currently accomplished every 30 days via TC's SB737-32-1448-NG-3/-4, AD20092407-800-32-3 and 20092604-NG-32-3,

TC SB737-32-1448-NG-1: LH FORWARD & AFT MLG TRUNNION PIN ASSY'S - INSPECTION / REPLACEMENT IN ACCORDANCE WITH WORK PACKAGE 2.	April 25, 2015
---	----------------

TC SB737-32-1448-NG-2: RH FORWARD & AFT MLG TRUNNION PIN ASSY'S - INSPECTION / REPLACEMENT IN ACCORDANCE WITH WORK PACKAGE 2.	April 25, 2015
---	----------------

Paragraph (j), LH/RH MLG Restoration TC's, unscheduled gear changes per TC 78732004 and IPC update will accomplish this paragraph.

Paragraph (j), for aircraft that accomplished Work Package 3, replace the MLG fwd trunnion pin housing assy seal, retainer & support ring at MLG OH , not to exceed 10 yrs from MLG installation after the most recent overhaul. This terminates AD 2019-01-03.

TC 161A1100-(XX) LM PNC: LEFT MAIN LANDING GEAR RESTORATION	July 17, 2018
---	---------------

TC 161A1100-(XX) RM PNC: RIGHT MAIN LANDING GEAR RESTORATION	July 17, 2018
--	---------------