




Left Horizontal Stabilizer Leading Edge (courtesy SWA)



Left Horizontal Stabilizer Spar (courtesy SWA)



Crack on Bottom face of Lower Spar Chord (courtesy SWA)