

NATIONAL TRANSPORTATION SAFETY BOARD
Investigative Hearing

Alaska Airlines Flight 1282

Boeing 737-9, N704AL

Left Mid Exit Door Plug Separation in Portland, OR

January 5, 2024

Docket No.	SA-543
EXHIBIT	
2J	

**Operational Factors Group
Chairman's Factual Report -
Attachment 9 - Alaska Airlines
Continuing Qualification 2025 LOFT
Simulator Profile**
(2 Pages)

DCA24MA063

OPERATIONAL FACTORS

Attachment 9

Alaska Airlines Continuing Qualification 2025 LOFT Simulator Profile

April 22, 2024

2025 CLO TRAINING PROFILE
Plan View (First Period)

