

ENGINE MODEL: PW4056
ENGINE/MODULE SERIAL NO.: 717684
SALES ORDER: ~~2717684-03~~ (NOTIF: 3000345617)

DATE: 07/11/2005
CUSTOMER NO.: 600334
CUSTOMER NAME: FLEET MANAGEMENT-NORTHWEST

SERVICE BULLETIN / MODIFICATION	R E V	C A T	COMPL LEVEL	S E T	SECTION	A C T	(BX) INDUCTION	(CX) INSPECT	(LX) LINE ASSY
PW4ENG-72-596 ✓	2	8	R		S3V (72-53-00-1)	V	PCW [REDACTED]	[REDACTED] 8/30/05	[REDACTED] 9/13/05 PCW
ENGINE - VANE CLUSTER ASSEMBLY, LOW PRESSURE TURBINE (LPT), 3RD STAGE - MODIFY THE INNER SUPPORT FLANGE TO REMOVE MATERIAL FROM TWO GUSSETS AND ADD A CHAMFER									
PREREQUISITE : PW4ENG-72-580									
PW4ENG-72-715 ✓		6	MP		S3V (72-53-00-1) S3B (72-53-03) S4V (72-53-00-1) S5B (72-53-05)	V	PCW [REDACTED]	[REDACTED] 8/30/05	[REDACTED] 9/13/05 PCW
ENGINE - AIRFOILS, 3RD, 4TH AND 5TH STAGE LOW PRESSURE TURBINE (LPT) INSPECTION OF, TO REMOVE PW4000-100 INCH AIRFOILS FROM PW4000-94 INCH ENGINES									

COMPLIANCE CODES:
M - MUST INCORPORATE
MP - INCORP IF PART EXPOSED
DEL- DELETE/REMOVE PART FROM ENGINE
AT - ATTRITION- INCORP IF PART REQUIRES NEW REPLACEMENT
NA - NOT APPLICABLE
R - INCORP WHEN PART NEEDS REPAIR

DISPOSITION CODES:
INC - INCORPORATED
NINC - NOT INCORP.
NA - NOT APPLICABLE
PCW - PREVIOUSLY COMPLIED WITH
NDNR - NOT DISASSY/NOT REQUIRED
DEL - REMOVED FROM ENGINE

MAINTENANCE LEVEL:
HVV - HEAVY MAINT.
LGT - LIGHT MAINT.
REP - REPAIR
VIS - VISUAL
ACTIONS:
A - ACCY
B - BIN
C - CLIP
E - ENGINE
G - BEARINGS
H - HARDWARE
K - KIT
T - TUBES
V - BLD & VANE

LEADPERSON SIGNOFFS:
BX LEADPERSON: [REDACTED]
*CX LEADPERSON: N/A
*REQUIRED ONLY IF BX DISPOSITION IS CHANGED
LX LEADPERSON: [REDACTED]
DATE: 7/22/05
DATE: 8/30/05
DATE: 09/14/05