

Dear Sir,

On Monday Sept 19th 2011 at approximately 10.00 AM while taking on Runway 5 at OBE, just as I approached the intersection for the ramp the port wheel strut let go causing the a/c to fall to that side. It caused the a/c to make a 180° turn and caused the prop to hit the ground, destroying it. Also the left wing hit the ground breaking the spar. I was not injured at all. The plane was removed from the runway by John Towing at 705 NE 2nd Ave. The A/c in question is 1993 Bakerq Deuce reg[#] N76GH. This information is to the best of my recollection.

Sincerely
[Redacted Signature]