



Photo 4 - Particulate Found Inside Left Carburetor (Photo Courtesy of Rotech)