

aircraft accident

From: Laurence Stone <[REDACTED]>  
Sent: Tuesday, May 07, 2013 12:43 PM  
To: Alleyne Eric  
Subject: aircraft accident

aircraft accident: may 2, 2013, baublitz airport, brogue, pa. a/c piper, cherokee 140, reg #33677.  
PIC laurence f. stone, cfi cert [REDACTED], 10/25/2011. student pilot randy shoemaker, no student pilot cert. runway 28, 2400' grass. wx clear, vis unlimited, winds light and variable mainly from 360, temp 55 fuel 38 gal.  
T0. at approx. 1015 full length of runway. student T0. initial T0 roll and acceleration to rotate speed normal. between 55 - 60 mph acceleration slowed. at 60 mph I told student to rotate. after approx 2-3 sec delay I assisted rotation to T0 attitude. at the end of the runway a/c struck power line at the end of the runway. approx 40 ft high. a/c made uncontrolled decent to farm field. both pilots required hospitalization. major damage to a/c. wind appeared to shift to tailwind during second half of T0 roll.  
PIC: tot hrs 18995, make and model 10 hrs last 6 mos 15 hrs, last year 30 hrs. all times approx.  
student pilot second flight.