



MEMORANDUM OF RECORD

Shawn Etcher
Air Safety Investigator
Eastern Region Aviation

March 24, 2015

Subject: ERA13LA221

At the time of this writing no response or statement was provided to the NTSB IIC by the pilot or a representative of the pilot. The following is a chronological order of contact made with either a family member of the pilot or an email sent to the provided pilot's email address:

- April 29, 2013 at 0950 EDT the NTSB communication center sent an email to the IIC that they had taken a phone call from the pilot's spouse for the above accident and provided the IIC with the phone number
- April 29, 2013 at 1131 EDT the IIC contacted the pilot's spouse, to which she stated that her husband was still in the hospital and that he would respond to my email. She provided the IIC with her husband's email address. She further reported that her husband had told her that the airplane would not respond to his commands while in flight
- April 30, 2013 at 0943 EDT an email was sent to the email address provided by the spouse requesting information of the events and contained the NTSB 6120 form. At 0944 EDT a "successfully delivered" email was received reporting that the email had been received by the pilot's email provider.
- May 1, 2013 at 1218 EDT an email was sent requesting a response of receipt from the previous email. No response was received from the pilot.
- May 3, 2013 at 1415 EDT a second email was sent requesting information from the pilot as well as providing a second NTSB 6120 form. At 1417 EDT a "successfully delivered" email was received by the IIC reporting that the email had been received by the pilot's email provider. However, at the time of the previous emails the NTSB Information Technology (IT) division reported an intermittent issue with outgoing emails.
- May 30, 1034 EDT, An email was sent to the pilot's email on record as provided by the spouse requesting information. As well as a telephone call to the last phone number on record, no response was received.

-END-