

According to statements by the staff of transit air, on the day of the accident at 1107 hours local, attempts to contact the pilot were unsuccessful. The flight did not arrive at its destination and a search was initiated. On November 24, 2012, the airplane was located. A post crash fire occurred.

This investigation is under the jurisdiction of the Government of Colombia. Any further information can be obtained from:

Unidad Administrativa Especial de Aeronautica Civil
Aeropuerto Internacional El Dorado
Bogota, Colombia
Telephone: 571.425.1000

This report is for informational purposes only, and contains information released by or obtained for the Government of Colombia.