



MEMORANDUM FOR RECORD

Stephen Stein
Air Safety Investigator
National Transportation Safety Board
Office of Aviation Safety - Eastern Region

Weather Report – Western Carolina Regional Airport (RHP), Andrews, North Carolina
Date & Time: July 10, 2014 1145 EDT
NTSB Accident Number: ERA14CA349

RHP is the nearest weather observation facility located at the accident site.

METAR/SPECI from KRHP, Andrews, Andrews-Murphy Airport (United States).	
SA 10/07/2014 20:55->	METAR KRHP 102055Z AUTO 05003KT 10SM SCT048 28/20 A3008 RMK AO2 T02800197=
SA 10/07/2014 20:35->	METAR KRHP 102035Z AUTO 00000KT 10SM CLR 28/20 A3008 RMK AO2 T02800195=
SA 10/07/2014 20:15->	METAR KRHP 102015Z AUTO 12003KT 10SM CLR 28/20 A3008 RMK AO2 T02770200=
SA 10/07/2014 19:55->	METAR KRHP 101955Z AUTO 13003KT 10SM SCT048 SCT055 29/20 A3008 RMK AO2 T02850199=
SA 10/07/2014 19:35->	METAR KRHP 101935Z AUTO 10003KT 10SM SCT050 BKN065 BKN080 28/20 A3009 RMK AO2 T02780201=
SA 10/07/2014 19:15->	METAR KRHP 101915Z AUTO 08004KT 10SM SCT035 BKN050 OVC065 26/20 A3009 RMK AO2 T02640203=
SA 10/07/2014 18:55->	METAR KRHP 101855Z AUTO 10004KT 10SM BKN036 OVC048 27/20 A3010 RMK AO2 T02660204=
SA 10/07/2014 18:35->	METAR KRHP 101835Z AUTO 00000KT 10SM SCT032 SCT040 BKN047 28/20 A3010 RMK AO2 T02770203=
SA 10/07/2014 18:15->	METAR KRHP 101815Z AUTO 27003KT 10SM SCT034 SCT047 BKN065 27/21 A3011 RMK AO2 T02650207=
SA 10/07/2014 17:55->	METAR KRHP 101755Z AUTO 27005KT 10SM SCT031 BKN040 BKN047 27/20 A3011 RMK AO2 T02690204 10275 20185=
SA 10/07/2014 17:35->	METAR KRHP 101735Z AUTO 24003KT 10SM SCT030 OVC040 27/20 A3012 RMK AO2 T02740204=
SA 10/07/2014 17:15->	METAR KRHP 101715Z AUTO 28006KT 10SM BKN030 BKN045 BKN090 27/21 A3013 RMK AO2 T02700209=
SA 10/07/2014 16:55->	METAR KRHP 101655Z AUTO 26006KT 10SM SCT110 27/21 A3014 RMK

		AO2 T02680207=
SA 10/07/2014 16:35->	METAR KRHP	101635Z AUTO 29004KT 10SM CLR 26/21 A3014 RMK AO2 T02600208=
SA 10/07/2014 16:15->	METAR KRHP	101615Z AUTO 29005KT 10SM SCT120 26/21 A3015 RMK AO2 T02560206=
SA 10/07/2014 15:55->	METAR KRHP	101555Z AUTO 29006KT 10SM CLR 25/21 A3014 RMK AO2 T02510210=
SA 10/07/2014 15:35->	METAR KRHP	101535Z AUTO 28005KT 10SM SCT095 25/21 A3015 RMK AO2 T02470208=
SA 10/07/2014 15:15->	METAR KRHP	101515Z AUTO 28004KT 10SM CLR 24/21 A3014 RMK AO2 T02380206=
SA 10/07/2014 14:55->	METAR KRHP	101455Z AUTO 29003KT 10SM CLR 23/20 A3014 RMK AO2 T02340201=
SA 10/07/2014 14:35->	METAR KRHP	101435Z AUTO 29003KT 10SM CLR 23/20 A3014 RMK AO2 T02250197=
SA 10/07/2014 14:15->	METAR KRHP	101415Z AUTO 00000KT 10SM CLR 22/19 A3014 RMK AO2 T02150186=
SA 10/07/2014 13:55->	METAR KRHP	101355Z AUTO 00000KT 10SM CLR 21/19 A3014 RMK AO2 T02110192=
SA 10/07/2014 13:35->	METAR KRHP	101335Z AUTO 00000KT 10SM BKN005 21/19 A3013 RMK AO2 T02060186=
SA 10/07/2014 13:15->	METAR KRHP	101315Z AUTO 00000KT 10SM BKN005 20/19 A3013 RMK AO2 T01990186=
SA 10/07/2014 12:55->	METAR KRHP	101255Z AUTO 04003KT 10SM BKN005 20/19 A3014 RMK AO2 T01950185=
SA 10/07/2014 12:35->	METAR KRHP	101235Z AUTO 00000KT 10SM BKN003 BKN033 19/18 A3013 RMK AO2 T01890184=
SA 10/07/2014 12:15->	METAR KRHP	101215Z AUTO 00000KT 10SM BKN003 OVC033 19/18 A3013 RMK AO2 T01880183=
SA 10/07/2014 11:55->	METAR KRHP	101155Z AUTO 00000KT 10SM OVC003 19/18 A3013 RMK AO2 P0001 60001 70107 T01850182 10192 20180=
SA 10/07/2014 11:35->	METAR KRHP	101135Z AUTO 00000KT 7SM OVC003 18/18 A3013 RMK AO2 P0001 T01820181=
SA 10/07/2014 11:15->	METAR KRHP	101115Z AUTO 00000KT 10SM OVC003 18/18 A3012 RMK AO2 P0001 T01810180=
SA 10/07/2014 10:55->	METAR KRHP	101055Z AUTO 00000KT 10SM OVC003 18/18 A3011 RMK AO2 T01800179=
SA 10/07/2014 10:35->	METAR KRHP	101035Z AUTO 00000KT 10SM BKN003 18/18 A3011 RMK AO2 T01800180=
SA 10/07/2014 10:15->	METAR KRHP	101015Z AUTO 00000KT 10SM SCT003 SCT090 18/18 A3010 RMK AO2 T01810180=