

TITLE

EQUIPMENT/FURNISHINGS - SEAT BELT BRACKET INSPECTION

TO:

Cessna 120 and 140 Owners

REASON

Cessna Aircraft Company wishes to update the seat belt bracket for airplanes in the field to the latest design.

DESCRIPTION

This service bulletin provides parts and instructions to do an inspection of the seat belt bracket and to replace it if necessary.

COMPLIANCE

MANDATORY. This service bulletin must be accomplished at the next 100-hour or 12-month (annual-type) inspection.

LABOR HOURS

No additional man-hours are required for the inspection.

If necessary, 0.7 man-hour is required to do the replacement of the seat belt bracket.

WARRANTY

Not applicable.

Please contact a Cessna Authorized Service Facility for detailed information and arrange to have Cessna service bulletin SEB-25-03 accomplished on your airplane.

Access the QR code for the instructional video link that follows or use the URL address:



Select this link:

<http://textron.vo.llnwd.net/o25/CES/CustomerService/SEB-25-03/SEB-25-03.html>

NOTE: As a convenience, service documents are now available online to all our customers through a simple, free-of-charge registration process. If you would like to sign up, please visit the "Customer Access" link at www.cessnasupport.com to register.

February 17, 2015

SEB-25-03
Page 1 of 1

Cessna Aircraft Company, Cessna Customer Service, P.O. Box 7706, Wichita, KS 67277, U.S.A. 1-316-517-5800

This document contains technical data and is subject to U.S. export regulations. This information has been exported from the United States in accordance with export administration regulations. Diversion contrary to U.S. law is prohibited. ECCN: 9E991

COPYRIGHT © 2015