

MAINTENANCE RECORD F.A.R. 43.9

DATE OF COMPLETION	AIRCRAFT TIME IN SERVICE	DESCRIPTION OF WORK PERFORMED OR APPROVED DATA USED	AGENCY & CERTIFICATE NO. WORK PERFORMED/RETURNED TO SERVICE
05/13/2013	405.4	I CERTIFY THAT THIS AIRCRAFT HAS BEEN INSPECTED IAW FK MAINTENANCE MANUAL & INSPECTION SCHEDULE FOR 100 HOUR CONDITION INSPECTION. RIGHT WING FUEL LEVEL TUBE REPLACED WITH PART SUPPLIED BY FK. FUEL FILTER REPLACED. AVIONICS POWER SWITCH REPLACED. CONTROL HINGE POINTS & LINKS LUBED. ALL SYSTEMS TESTED. AIRCRAFT FOUND TO BE IN A CONDITION FOR SAFE FLIGHT. LSRMA	
05/11/2013	503.0	I CERTIFY THAT THIS AIRCRAFT HAS BEEN INSPECTED IAW FK MAINTENANCE MANUAL AND INSPECTION SCHEDULE FOR ANNUAL CONDITION INSPECTION. MINOR CRACK IN PILOTS SEAT BACK REPAIRED IAW FK DIRECTIONS. FLAP SWITCH REPLACED WITH FK FACTORY SUPPLIED PART LORLIN CH1039. ALL CONTROL HINGE POINTS & LINKS LUBED. ALL SYSTEMS TESTED. AIRCRAFT TEST RUN AND FOUND TO BE IN A CONDITION FOR SAFE FLIGHT. LSRMA	