

United States of America
Department of Transportation -- Federal Aviation Administration
Supplemental Type Certificate

Number SH529SW

This certificate issued to

Texas Helicopter Co., Inc.
140 Washington Ave.
Mineral Wells, TX 76067

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 6 of the Civil Air Regulations.

Original Product -- Type Certificate Number: H-1
Make: Bell
Model: 47D1

Description of Type Design Change:

Installation of Franklin 6V-350A engine in accordance with Installation Instruction No. 15 revised July 26, 1965.

Limitations and Conditions:

FAA Approved RFM Supplement dated 6/30/65 is required.
Compatibility of this design change with previously approved modifications must be determined by the installer. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: June 24, 1965

Date of issuance: June 26, 1965

Date reissued: 3/4/86; 7/27/87; 4/30/04

Date amended: 2/7/66; 11/22/74 Rev. 2



By direction of the Administrator

(Signature)
Carl F. Mittag, Manager
Rotorcraft Certification Office,
Southwest Region

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.