

**NATIONAL TRANSPORTATION SAFETY BOARD
MATERIALS LABORATORY DIVISION
RECEIPT OF RETURNED PARTS**

ACCIDENT/INCIDENT IDENTIFICATION		
PLACE:	Suffolk, VA	
DATE / VEHICLE:	5/31/2014	Vans RV-6, N6RP
NTSB NO. / IIC:	ERA14LA272	Stephen Stein, ERA
THE FOLLOWING PARTS, PIECES OR COMPONENTS, FROM THE ABOVE ACCIDENT/INCIDENT		
Pieces from propeller hub and pieces of propeller blades		
ARE BEING RETURNED VIA U.S. REGISTERED MAIL NO.:		UPS 1Z-A4E-715-01-9189-1983 1Z-A4E-715-01-9220-9790
OR BY OTHER CARRIER (NAMED)		1Z-A4E-715-01-9372-0207
WHICH HAS BEEN ADDRESSED TO:		
NAME :	George McClellan	
COMPANY:	Recovery Services	
ADDRESS :		

RECIPIENTS PLEASE VERIFY THAT THE COMPONENTS, AS ITEMIZED, HAVE BEEN RECEIVED BY PRINTING LEGIBLE YOUR NAME, SIGNING, AND DATING THIS FORM BELOW, AND RETURNING THIS DOCUMENT TO: *Mike Budinski, CHIEF, MATERIALS LABORATORY DIVISION, (RE-30), NATIONAL TRANSPORTATION SAFETY BOARD, 490 L'ENFANT PLAZA EAST, WASHINGTON, D.C. 20594.* ATTACHED IS A SELF-ADDRESSED, STAMPED ENVELOPE FOR YOUR CONVENIENCE.
IF ANY DISCREPANCIES ARE FOUND, IMMEDIATELY CALL (202) 314-6530.

WRITER'S NAME AND INITIALS	Budinski	DATE 11Sep2014
NTSB REPRESENTATIVE PACKING PARTS	Budinski	DATE 11Sep2014
NAME AND SIGNATURE OF RECIPIENT OR RECIPIENT'S REPRESENTATIVE	Print Sign	DATE

Part Return Form.doc (Word Template)