


CARBURETOR ICING ENVELOPE



er

Source: FAA SAIB CE-09-35; June 2009