


CARBURETOR ICING ENVELOPE



Source: FAA SAIB CE-09-35; June 2009