

On April 30, 2014, at 0318 Coordinated Universal Time (UTC), a Robinson R44 II, Russian registration RA-06217, impacted terrain, near Inta, Russia. The pilot was fatally injured.

The investigation is under the jurisdiction of the Russian Federation Interstate Aviation Committee.

Further information can be obtained from:

Interstate Aviation Committee

22/2/1 Bolshaya Ordynka Str.,

Moscow, Russia

Website: www.mak.ru

This report is for informational purposes and contains only information released by the Russian Federation