



Photo 2 – View of Damage to Tail Rotor (Photo Courtesy of Flight Instructor)