



MEMORANDUM FOR RECORD

Stephen Stein
Air Safety Investigator
National Transportation Safety Board
Office of Aviation Safety - Eastern Region

NTSB Accident Number: ERA15CA100
Aircraft Registration & Make/Model: N32SN; Vans RV-6
Accident Location: Pikeville, Kentucky
Accident Date: January 14, 2015

Note: The following interview was completed by the Investigator –In-Charge (IIC).

Interview Summary

Patrick Pauley
Federal Aviation Administration Inspector

Interview date/time: January 15, 2015; 1402 EST
Telephone

Interviewer was Stein.

Mr. Pauley reported the presence of rime ice on the leading edges of the wings, horizontal stabilizer, and vertical stabilizer at the accident site. The rime ice was observed through photos that had been taken by the airport manager shortly after the accident.