



MEMORANDUM OF RECORD

NTSB Accident Number: ERA15FA096, Cataño, Puerto Rico

Email Excerpt:

From: Thom Webster [Robinson Helicopter]
Sent: Thursday, December 15, 2016 1:29 PM
To: Cox Paul

A rapid increase in Engine RPM along with a slight over speed can create white smoke out the exhaust, especially in a higher time engine. This requires the pilot to override (or turn off) the governor.

Paul R. Cox
Investigator in Charge