

Cox Paul

From: McAtee Nancy
Sent: Tuesday, November 08, 2016 2:32 PM
To: Cox Paul
Cc: Budinski Michael
Subject: Email report-ERA15FA096
Attachments: ALT ERA25FA096.jpg; GOV Off ERA15FA096.jpg; OIL P ERA15FA096.jpg

Paul,

Six light bulbs from the annunciator of the accident aircraft were submitted to the Materials Laboratory for examination. The bulbs were submitted to determine the presence of hot filament stretching on the individual light bulb's filament. Of the six submitted, three were found to have filament stretching present- the ALT bulb, the GOV OFF bulb and the OIL P bulb. The radiographs of the stretched filaments are attached to this email. If you have any question, please feel free to contact me.

Nancy B McAtee
Chemist
RE-30