

Complaints Related to N465JA

- Apache 465JA
- Collided with turkey buzzard, damage was major, pulled inboard wing back to spar.
- Gear collapsed recently during hand tow into hangar, damaged flaps and gear.
- Both engines failed during climb out after fuel pumps were turned off.
- Keys, fuel caps, and other debris found by instructor in fuel tank.
- Generators removed and replaced with sky-tek alternators
- Right engine mount broke
- brakes fail weekly