

□ USAirports Flight Support 1265 Scottsville Road Rochester, NY 14624 UG6R0850
LOG ID# 1174 06-November-2014 WO# 6129 AC TT 1294.5
Ye N819TB S/N 4697117 PIPER PA46-500TP TSMOH 188.9

Pg 11

Da DISCREPANCY: Annual inspection

A. ACTION: Performed an Annual Inspection (Event #1 and Event #2) using a checklist that meets the requirements of CFR 43 appendix D.

DISCREPANCY: AD research required

Na ACTION: Performed and completed AD research IAW Tdata disc up to and including 2014-22.

Di DISCREPANCY: Beta ring carbon block worn

ACTION: Removed carbon block p/n A-3026. Installed new carbon block p/n A-3026 IAW 61-10-00.

DISCREPANCY: Prop deice boot has nick and delaminating

Ye ACTION: Found nick and seperation acceptable per PA46-500TP MM 30-60-00. Nick and seperation sealed with edge sealant.

Di DISCREPANCY: Wing and prop deice boots missing edge sealer

A. ACTION: Applied edge sealant to prop and wind deice boots per 30-10-00 and Hartzell manual 61-12-82.

Items approved for return to service. Pertinent details are on file at this repair station under the work order mentioned above.

Di

CRS UG6R0850 Dennis Gray

Date