

Skytech, Inc. - DMW

Carroll County Regional Airport

200 Airport Drive

Westminster, MD 21157

Tel: (410) 574-4144 Fax: (410) 848-6451

CRS LF1R294K www.skytechinc.com

Invoice: DMW-102362

Opened: 7/02/2015

Closed: 7/13/2015

Sold To: Ray Shortino

Rochester, NY 14610 United States

Handwritten:
 Pd Rep
 Mastercard
 7/14/15

Aircraft Number: N819TB

Type: PA-46-500TP

S/N: 4697117

Total Time:

Hobbs Time: 1,388.8

Tach Time:

LG Cycles:

Eng# Type

S/N

Time Cycles

Prop Type

Prop S/N

Prop Time

1 PT6A-42A

PCE-RM0122

Squawk: 100

Problem:

Autopilot only trims in one direction

Action Taken:

Removed S-TEC 55X Pitch servo p/n 0108-15-P4, s/n 10158, installed repaired Pitch servo p/n 0108-15-P4, s/n 12454 (S-TEC crs#FF2R818K, w.o.#R000079090, date 11/Dec/2014) IAW Piper PA-46-500TP ch.22-10-00

Charges This Item:

3.50 Hours @ 108.00 \$ 378.00

Part Number	Description	Credit	Quantity	Units	List Price	Disc	Unit Price	Extended
0108-15-P4	Pitch Servo (Exch.)		1.00	Each	1,674.000		1,674.000	\$ 1,674.00
	S/N: 12454							
	Freight		1.00				78.090	\$ 78.09
Total For This Squawk:								\$ 2,130.09

Squawk: 101

Problem:

Pilot Trim switch button broken.

Action Taken:

Replaced pilot yoke trim switch cap with new unit p/n 5808-01, 5808-02 IAW Piper PA-46-500TO AMM ch.22-10-00

Charges This Item:

0.50 Hours @ 108.00 \$ 54.00

Part Number	Description	Credit	Quantity	Units	List Price	Disc	Unit Price	Extended
5808-1	Button, Trim, Left Half "TR"		1.00	Each	79.950		79.950	\$ 79.95
5808-2	Button, Trim, Right Half "IM"		1.00	Each	79.950		79.950	\$ 79.95
Total For This Squawk:								\$ 213.90

Squawk: 102

Problem:

LH boost pump inop

Action Taken:

Replaced LH fuel pump module with new unit p/n 102227-007 IAW Piper SB 1166, dated 1/5/07.
 Repaired one wire at connector P117 in LH wing.

Charges This Item:

5.00 Hours @ 108.00 \$ 540.00

Part Number	Description	Credit	Quantity	Units	List Price	Disc	Unit Price	Extended
102227-007	SB1166 Module Assy. M+		1.00	Each	483.570		483.570	\$ 483.57

Printed: 7/13/2015

Invoice: DMW-102362

Page: 1 of 2