

DAILY RECORD OF FACILITY OPERATION				PAGE NO Page 1 of 2
				DATE Aug 27, 2015
LOCATION Nashua, NH	IDENTIFICATION ZBW	TYPE FACILITY ARTCC	OPERATING POSITION OMIC	CHECKED BY AIR TRAFFIC MANAGER Peter S. Abbey
UTC TIME	REMARKS			
0400	R. Taylor on. CFPL: PWM ATCT and APCH are Long Term ATC ALERT for Stairwell Pressurization Issue.127.37 Main/Standby Scratchy and unusable, operating on BUEC, Tech Ops notified -- XR			
0430	ERAM Channel Promotion. Channel A Active -- XR			
0445	ERAM Backup channel RTM. -- XR			
0455	ZBW-M-2015/08/27-0001 -- N430QS -- XR			
0509	ERAM Backup channel RTS. -- XR			
0844	J. Cooper on -- JC			
1221	Delayed entry: 08/26/2015 at 14:30Z FMH ARTS RTS -- JC			
1300	QRC RTM -- JC			
1315	Location confirmed for overdue aircraft N553MD into HUL . Pilot of N9544Q inbound into HUL advised ZBW that the aircraft had been found and they were flying in to investigate. ZBW OM called Houlton ME state police and received confirmation that N553MD was down in a residential pond (upside down). Houlton State Police contact confirming aircraft down is LT Brian Harris [REDACTED]. Aircraft location: 355 White Settlement Rd. Houlton, ME. -- JC			
1406	Request for N553MD ALNOT CNLD forwarded to BGR FSS. N553MD ALNOT CNLD at 1357Z -- JC			
1427	ACR BCN Search removed from primary channel (for clutter) -- JC			
1600	A. Velazquez on, above noted. -- VZ			
1603	QRC RTS. -- ZX			
1650	HUL RY 5 PAPI RTM UFA due to post accident investigation. -- VZ			
1653	Area A Operational Currency Dashboard Reviewed. Employees On Duty Needing Currency Notified. -- VZ			
1653	Area B Operational Currency Dashboard Reviewed. Employees On Duty Needing Currency Notified. -- VZ			
1653	Area C Operational Currency Dashboard Reviewed. Employees On Duty Needing Currency Notified -- VZ			
1653	Area D Operational Currency Dashboard Reviewed. Employees On Duty Needing Currency Notified -- VZ			
1653	Area E Operational Currency Dashboard Reviewed. Employees On Duty Needing Currency Notified -- VZ			
1653	TMU Operational Currency Dashboard Reviewed. Employees On Duty Needing Currency Notified. -- VZ			
1736	ZBW-M-2015/08/27-0002 -- RPA4902/RLI331 -- VZ			
I CERT FY that entries above are correct, that all scheduled operations have been accomplished except as noted, and that all abnormal occurrences and conditions have been recorded.		SIGNATURE(S) OF WATCH SUPERVISOR(S)		

DAILY RECORD OF FACILITY OPERATION				PAGE NO Page 2 of 2
				DATE Aug 27, 2015
LOCATION Nashua, NH	IDENTIFICATION ZBW	TYPE FACILITY ARTCC	OPERATING POSITION OMIC	CHECKED BY AIR TRAFFIC MANAGER Peter S. Abbey
UTC TIME	REMARKS			
1900	Michael Dillon OMIC. -- ZX			
2116	ZBW-M-2015/08/27-0003 -- UCA4848 -- ZX			
2203	ZBW-M-2015/08/27-0004 -- W0W125 -- ZX			
2230	A. Velazquez on, above noted. -- VZ			
2324	Area A Operational Currency Dashboard Reviewed. Employees On Duty Needing Currency Notified. -- ZX			
2324	Area B Operational Currency Dashboard Reviewed. Employees On Duty Needing Currency Notified. -- ZX			
2324	Area C Operational Currency Dashboard Reviewed. Employees On Duty Needing Currency Notified. -- ZX			
2324	TMU Operational Currency Dashboard Reviewed. Employees On Duty Needing Currency Notified. -- ZX			
2325	Area D Operational Currency Dashboard Reviewed. Employees On Duty Needing Currency Notified. -- ZX			
2325	Area E Operational Currency Dashboard Reviewed. Employees On Duty Needing Currency Notified. -- ZX			
0000	EBUS RTM. -- ZX			
0013	Normal Ops Verified - DALR. WCLC. -- ZX			
0200	A.Szczawinski on as above noted -- AS			
0359	C.O.B. -- AS			
I CERT FY that entries above are correct, that all scheduled operations have been accomplished except as noted, and that all abnormal occurrences and conditions have been recorded.		SIGNATURE(S) OF WATCH SUPERVISOR(S)		