



Photo 1 – Helicopter (Photo Courtesy of FAA)



Photo 2 – Tail Boom Damage (Photo Courtesy of FAA)



Photo 3 – Section of Tail Rotor Driveshaft