



MEMORANDUM FOR RECORD

Allison Diaz
Air Safety Investigator
Office of Aviation Safety – Eastern Region

Date: August 7, 2015
NTSB Accident Number: ERA15LA248
Persons Contacted: Inspector Ric Riccardi, FAA Orlando FL FSDO

Inspector Riccardi provided the following information regarding the accident:

- An engine run was performed at Florida Air Recovery, Jacksonville, Florida, on August 7, 2015.
- The engine was fitted with a replacement carburetor and propeller before the test was conducted, since the original components were damaged during the accident.
- A test run was conducted with no anomalies in engine operation noted. The fuel used during the test was not from the accident airplane.

END