



Memorandum of Record

NTSB Accident Number: ERA15LA306, Brooksville, Florida

In initial discussions with Federal Aviation Administration Inspector Linda Nevin, and as confirmed by email October 19, 2016, the airplane was too damaged by fire to conduct extensive engine and related systems examinations.

Paul R. Cox
Senior Air Safety Investigator