

Lapeer Aviation Inc.



Lapeer, MI 48446

Invoice

Bill To:

Mike Moir



PAID

Invoice 39451

Invoice Date 6/12/2015

Due Date: 6/12/2015

P.O. No.

Item	Description	Hours/Qty	Rate	Amount
CH48109-1	OIL FILTER(LIST=\$36.80)	1		
OILXC20W50	PHILLIPS OIL	9		
CI-105	Comant CI-105 DME/Transponder Antenna	1		
6000-12	Hose	3		
O2 charge	O2 charge	1		
23835	Voltage Regulator	1		
A350CN	post light	2		
SHIP	SHIPPING/HANDLING	1		
0005-0	Exhaust transition	1		
ANNUAL	100 hour annual inspection	1		
0002-0	Troubleshoot and repair instrument lights A&P LABOR	5		
0002-0	Troubleshoot and adjust gear warning switch A&P LABOR	1.5		
0002-0	Adjust mag timing A&P LABOR	1		
0002-0	Adjust Turbos for MP and adjust idle mixture A&P LABOR	1.5		
0002-0	Replace exhaust transition A&P LABOR	4		
0002-0	Replace breather hose A&P LABOR	0.75		
0002-0	Replace Transponder antenna A&P LABOR	0.25		
0002-0	Replace intake drain line on left side A&P LABOR	1		
	Sales Tax			
		Total		
If any additional charges are billed to Lapeer Aviation for warranty or core charge parts the customer will be billed upon notice from the manufacturer or overhaul facility.		Payments		
		Balance D		

Lapeer Aviation Inc.

[REDACTED]
Lapeer, MI 48446

Invoice

Bill To:

Mike Moir
[REDACTED]

PAID

Invoice 39452

Invoice Date 6/15/2015

Due Date: 6/15/2015

P.O. No.

Item	Description	Hours/Qty	Rate	Amount
IFR Certification	IFR Certification Sales Tax	1		[REDACTED]
			Total	[REDACTED]
If any additional charges are billed to Lapeer Aviation for warranty or core charge parts the customer will be billed upon notice from the manufacturer or overhaul facility.			Payments/C	[REDACTED]
			Balance Due	\$0.00