

Pt is a 23 y/o male that was flying from Morristown, NJ and did a touch & go from Butter Valley Golf/Airfield or a fly over when bystanders say they heard is engine sputter. From bystanders, the pt flew over the high tension power lines and as the engine cut out tried to turn back towards the direction of Butter Valley. Per bystanders the plane was loosing altitude quickly and dropped under the high tension lines. Once just barely clearing them, bystanders say he then had to make it through the high tension towers and did. Then the plane came down in a hard landing, per bystanders and then drove its nose into the ground, bounced up and again drove the nose into the ground, bounced and when it hit next it drove the nose of the plane into a hot cattle fence and started to cartwheel approx. 3x +. Bystanders say it then flipped over. By the time the witnesses made it to the plane, EMS & Fire were arriving. Pt is standing on the wing of the plane at time of arrival. Please refer to the flow chart for further detail.